

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. No. 197 on the B.E. "West" Survey held at London Date, first Survey 1876 Last Survey 23-Sept 1876

TONNAGE under Tonnage Deck Built at Sunderland When built 1848
Ditto of Spar Deck, or Awning Deck Owners J. Santy Port belonging to London
Ditto of Poop Residence 24 C. H. Daff, 409
of Rai. r. Dk. on Deck 360
castle
as per Rule
Tonnage, cut on Beam
Room
Tons as St. er, cut on m.
By whom built Destined Voyage
If Surveyed Afloat or in Dry Dock Afloat Millwall etc

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 13 9 9
Classed 13 9 9 Character in Register Book. A1 Rec Miller 12-73

Last Survey No. 33645 Port London REPAIRS, OR EXAMINATION, UNDER RULE

At owners request examining her for entry of class. - Ballast under main hatch before and after such found the cutting in a very bad condition. Decks shabby and pieces. Ripping requires overhauling. - Boats want repairs. wrote owners same day as follows

Having this day in accordance with your request surveyed your vessel the "West" now lying in the Millwall dock we beg to inform you that it will be necessary before she can be reclassified that she be placed in dry dock. the defective ceiling in hold renewed and through fastened. Stages made between decks for examination of those parts and the deck as far as may be found necessary

Present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
	Keelsons	Sails
	Clamps and Shelves	Anchors No. of
	Ceiling	Cables
	Rudder	Hawsers and Warps
	Copper When put on	Standing & Running Rigging
	Caulking of	
Bottom (Bottom) and Counter	Bottom, Deck, & Waterways	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways	Hatches

The owner not having complied with our recommendations we are unable to submit her for the Committee's consideration for the entry of class

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ : : 187
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)

Committee's Minute 15th Sept 1876
Character assigned 1876
will be recommended
marks repaired
points to be repaired
for a few days

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

LONG 61-0356

referred

Signed

Wm. L. Baver

J. W. Scullard

Committee's Minutes 10th October, 1876

Minutes assigned



© 2021

Lloyd's Register
Foundation