

ANNUAL SURVEYS.

33,732
Rev 26-9-76

No. in **No.** Survey held at London Date, first Survey _____ Last Survey Sept 18th 1876
 Reg. Book. on the S Torrens Master _____
397 Tonnage 1276 Built at Sunderland When built 1875 10
 By whom built Sainy Owners A L Elder
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 10249 Port of Sunderland Classed 16A1 1175
 Present Condition of the
 Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. When put on 1875
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Patched new
Bottom, Deck, & Waterways Good
 Windlass and Capstan "
 Pumps "
 Boats "
 Masts, Yards, &c. Good &
 Condition, how ascertained sufficient
 Sails where
 Anchors, No. of 3 B. & 1 H. they
 Cables could
 Hawser and Warps be seen
 Standing and Running Rigging "

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martinade

Committee's Minute 29 September 1876
 Character assigned 10A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. Survey held at London Date, first Survey _____ Last Survey Sept 16 1876
 No. in Reg. Book. on the S Caranjah Master _____
202 Tonnage 851 Built at Sunderland When built 1863 12 M
 By whom built Smiththorpe Owners E Hughes
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock Part of hull and cargo in

Last Survey, No. 34837 Port of London Classed 11A1 775
 Present Condition of the
 Decks Good Treenails Where seen Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. When put on 1875
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good
Bottom, Deck, & Waterways Good
 Windlass and Capstan "
 Pumps "
 Boats "
 Masts, Yards, &c. Good &
 Condition, how ascertained sufficient
 Sails where
 Anchors, No. of 3 B. & 1 H. they
 Cables could
 Hawser and Warps be seen
 Standing and Running Rigging "

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martinade

Committee's Minute 29 September 1876
 Character assigned Cout 7A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____