

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. No. 238 Survey held at S Carmarthenshire Date, first Survey Sept 5 Last Survey Sept 26 1876

Master

TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Avoing Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St'mer, cut on Bm.

Built at Pembroke Dock When built 1865
Owners J Jenkins Port belonging to London
Residence
By whom built Long Destined Voyage
If Surveyed Afloat or in Dry Dock Dry Dock outwards Cargo in

Length of Poop 47 ft. Ditto, Forecastle 27 ft. Ditto, Raised Quarter Deck ft.
Last Survey, No. 34783 Port London
Classed 14 H. 6. 75
HT Lon 72

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the vessel placed in dry dock the yellow metal stripped off the bottom & caulked from the keel to top of Wales and reyellow metalled on felt to load line.
9 main deck planks renewed with Pitch Pine.

Present Condition of the
Decks Good
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights
Coal Bunker, Openings, Lids, &c.
Scuppers
Cargo and Main Hatchways
Hatches
Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging

General Observations, Opinion as to Class, &c.
She is now in an efficient state of repair and entitled to remain as classed.

Senhouse Martindale

Amount of Entry Fee ... £ 2 : 2 : received by me, 4/11/76
Special ... £ 2 : 2 :
Certificate (if required) ... £ : :
Lloyds Expenses, if any, £

Committee's Minute 6th October 1876
Character assigned 14 H. 6. 75

Surveyor to Lloyd's Register of British and Foreign Shipping.
© 2021
Lloyd's Register Foundation

LONG 661-0396