

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 21<sup>st</sup> Oct<sup>r</sup> Last Survey 13<sup>th</sup> Nov<sup>r</sup> 1876

584 on the "Jubilee" Master Allen

Official Number	TONNAGE under Tonnage Deck <u>739</u>	Built at <u>Workington</u>	When built <u>1854</u>
	Ditto of Spar Deck, or Awning Deck	Owners <u>J. Brodie</u>	Port belonging to <u>London</u>
	Ditto of Poop	Residence	
	Ditto of Raised Qr. Dk.	By whom built	Destined Voyage
	Ditto of Houses on Deck	If Surveyed Afloat or in Dry Dock <u>Regent dry dock</u>	
	Ditto of Forecastle		
	Gross Tonnage <u>765</u>		
	Crew Space, as per Rule		
	Register Tonnage, cut on Beam <u>765</u>		
	Engine Room		
	Reg. Tons as St <sup>r</sup> mer, cut on Bm.		

Length of Poop ✓ ft. Ditto, Forecastle ✓ ft. Ditto, Raised Quarter Deck 45 ft. Years assigned. 14 Character in Register Book. A1 5-75

Last Survey, No. 34970 Port London Classed Col 71-940

## REPAIRS, OR EXAMINATION AS PER RULE

(Docked for examination of Bottom and found satisfactory. Main Rail renewed from the fore to the Mizzen rigging. The main mast replaced with a new one.

Surveyed with damage in hold and Coals in peak.

Cause of Repairs to be clearly stated



© 2021

Lloyd's Register Foundation

LONG66-0413 1/2

Lon. 35 770<sup>A</sup>

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails *where seen Good*

Breasthooks and Stemson *de de*

Transoms, Pointers, and Crutches *de de*

Timbers of the Frame at the openings *de de*

Ditto Ditto at other places *de de*

Keelsons *de de*

Clamps and Shelves *de de*

Ceiling *de de*

Rudder *de de*

Copper *4-0* When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

*This Ship appears in good Condition. With regard to the application of the Owner that the H.T. Survey may be deferred until the vessel's return I beg to submit that it may receive the favorable consideration of the Committee, with the view to the class remaining undisturbed for the present voyage.*

The Amount of Entry Fee ... £ ... : : received by me, }

*27/11/76* Special ... £ 2 : 2 : 187 }

Certificate (if required) ... £ ... : :

(Travelling Expenses, if any, £ ... )

Committee's Minute *21<sup>st</sup> November 1876*

Character assigned *Ant 7179 A.1.*

*Gen Com*

*H. Couadon*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LONG 661-0413 2/2

300-217176-1  
Surveys are required not to write on or below the space for Committee's Minute.)

Jubilee



© 2021

Lloyd's Register  
Foundation