

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 183 on the *Sch^r Welsh Girl* Master *J. Bradley*
 Survey held at *London* Date, first Survey *21st 11th* Last Survey *27th Dec^r 1876*
 Tonnage under Tonnage Deck *137* Built at *Harvey* When built *1863* YEAR. MONTH.
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *137* Owners *A. M. Gillespie* Port belonging to *London*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam *137* By whom built *Harvey* Destined Voyage
 Engine Room
 Reg. Tons as St^rmer, cut on Bm.
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Length of Poop *—* ft. Ditto, Forecastle *—* ft. Ditto, Raised Quarter Deck *—* ft. Years assigned. Character in Register Book.
 Last Survey, No. *34712* Port *London* Classed *11A 475*
Genl Serv July 76-490

REPAIRS, OR EXAMINATION AS PER RULE

at the present time placed in Dry Dock the Yellow Metal stripped off the bottom & caulked from keel to top of Y Metal. The following is damage Repair (Yellow Metal excepted) Starboard side 3 Roughtree Stanchions Eng Oak, 1 length of plank sheen Eng Oak. Waterway inside of Stern Eng Oak. Saffrail Beam fitted and well connected to Stern timber and Roughtree Stanchions. Caulked from Yellow Metal to funnel. Roughtree Stanchions. Waterways & part of Deck. Re Yellow Metal on felt to load line

Present Condition of the	Good	Treenails	Good	Windlass and Capstan
Decks	✓	Breasthooks and Stemson	✓	Pumps
Waterways	✓	Transoms, Pointers, and Crutches	✓	Boats
Comings	✓	Timbers of the Frame at the openings	✓	Masts, Yards, &c.
Upper Deck Beams & Fastenings	✓	Ditto Ditto at other places	✓	Condition, how ascertained
Lower Deck Beams & Fastenings	✓	Keelsons	✓	Sails
Plank sheers	✓	Clamps and Shelves	✓	Anchors No. of <i>1 No. 21 No. 14</i>
Sheerstrakes	✓	Ceiling	✓	Cables
Topsides	✓	Rudder	✓	Hawsers and Warps
Wales	✓	Copper <i>Y Metal</i> When put on <i>Now</i>	✓	Standing & Running Rigging
Plank (Bottom) and Counter	✓	on felt to load line	✓	Cargo and Main Hatchways
Engine Room Skylights	✓	Caulking of	✓	Hatches
Coal Bunker, Openings, Lids, &c.	✓	Bottom, Deck, & Waterways	✓	
Scuppers	✓		✓	

General Observations, Opinion as to Class, &c. *She is now in an efficient state of repair and entitled to remain as classed*

Survey Dec 22-20
 The Amount of Entry Fee ... £ 2 : 2 : received by me, *21 Dec 1876*
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)
 Committee's Minute *22nd December 1876*
 Character assigned *Good*
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 © 2021 Lloyd's Register Foundation
 LONGG1-0447