

ANNUAL SURVEYS.

35951

No. in Reg. Book. **611** No. **35042** Survey held at London Date, first Survey _____ Last Survey July 13 1877
 on the Royal Irish Master _____
 Tonnage 285 Built at Bideford When built 1872 4M
 By whom built Cox Owners J. A. Murray
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 35042 Port of London Classed 15A 10.75
 Present Condition of the Decks Good Treenails Good
 Waterways ✓ Breasthooks and Stemson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shelves ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Y Metal When put on 1875
 Engine Room Skylights ✓ Caulking of Bottom, Deck, & Waterways Good
 Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in an efficient state of repair and entitled to remain as Class

Committee's Minute 20th February 1877 Samuel Martin
 Character assigned 15A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **580** No. **1027** Survey held at London Date, first Survey _____ Last Survey Jan 16 1877
 on the Hurma Master Pearson
 Tonnage 382 Built at Foreign When built _____
 By whom built _____ Owners J. J. Robt.
 Port belonging to N. Shields Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 1027 Port of London Classed A1 7.76
 Present Condition of the Decks Good Treenails Good
 Waterways ✓ Breasthooks and Stemson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shelves ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. _____ When put on _____
 Engine Room Skylights ✓ Caulking of Bottom, Deck, & Waterways Good
 Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in an efficient state of repair and entitled to remain A1 as Class

Committee's Minute 20th February 1877 Samuel Martin
 Character assigned A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

5100-209207