

# REPORT of SURVEY for REPAIRS, &c.

\*36,177

(Recd 11.5.77)

No. in Reg. Book. **No.** 617 on the **PS Brierly Hill** Survey held at **London** Date, first Survey \_\_\_\_\_ Last Survey **10 May** 18**77**

Master \_\_\_\_\_

YEAR. MONTH.

TONNAGE under Tonnage Deck \_\_\_\_\_ Built at **Sunderland** When built **1858**

Ditto of Spar Deck, or Awning Deck \_\_\_\_\_

Ditto of Poop \_\_\_\_\_

Ditto of Raised Qr. Dk. \_\_\_\_\_ Owners **Hudson Bay Co** Port belonging to **London**

Ditto of Houses on Deck \_\_\_\_\_

Ditto of Forecastle \_\_\_\_\_ Residence \_\_\_\_\_

Gross Tonnage \_\_\_\_\_

Crew Space, as per Rule \_\_\_\_\_ By whom built \_\_\_\_\_ Destined Voyage \_\_\_\_\_

Register Tonnage, cut on Beam **520** ~~If Surveyed Afloat or in Dry Dock~~ **Limehouse dock**

Engine Room \_\_\_\_\_

Reg. Tons as St' mer, cut on Bm. \_\_\_\_\_

Length of Poop \_\_\_\_\_ ft. Ditto, Forecastle \_\_\_\_\_ ft. Ditto, Raised Quarter Deck \_\_\_\_\_ ft.

Last Survey, No. **35167** Port **London**

REPAIRS, OR EXAMINATION AS PER RULE \_\_\_\_\_

Classed **W A 1** Years assigned **11.75** Character in Register Book **Exp'd & omitted**

Cause of Repairs to be clearly stated.

This vessel has been into dry dock, but not submitted for survey.

With reference to the Secretary's letter to the Comdant. dated 20<sup>th</sup> Feb 1877 respecting the Restoration of the vessel, it has been decided by the Company to defer reclassing until some future period.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.	Coal Bunker, Openings, Lids, &c.	Scuppers
		Hatches

The Amount of Entry Fee ... ..£ : : received by me, }  
 Special ... ..£ : : 187 }  
 Certificate (if required) ... ..£ : :  
 (Travelling Expenses, if any, £ .....)

Committee's Minute ..... 18

Character assigned .....

*Thos. Cropper*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.