

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** *510* on the *S. Mars* Survey held at *London* Date, first Survey *28 June* Last Survey *3 July* 18*77*
 Master *Homan*
 Tonnage under Tonnage Deck *651*
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *722*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam *722*
 Engine Room
 Reg. Tons as St'mer, cut on Bm.
 Built at *Sunderland* When built *1856*
 Owners *S. H. Allan* Port belonging to *London*
 Residence
 By whom built
 Destined Voyage
 If Surveyed Afloat or in Dry Dock *Line Rtn dry dock*

Length of Poop *54* ft. Ditto, Forecastle *36* ft. Ditto, Raised Quarter Deck
 Last Survey, No. *354* Port *London*
 Classed *14* At *4.76*
 Character in Register Book. *Cal 40-942*
H.T. 46.

REPAIRS, OR EXAMINATION AS PER RULE
Yellow trestle stripped off. Caulked from keel to the upper part of wales, and the four upper seams Caulked. Re-hutalled over felt as before.

Present Condition of the			
Decks	} <i>Good</i>	Treenails	} <i>Good</i>
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	} <i>Complete</i>
General Observations, Opinion as to Class, &c.			

This vessel appears in good condition and eligible to remain as classed.

Amount of Entry Fee ... £ ... received by me, *W. H. Congdon*
 18/7/77 Special ... £1:11:00
 Certificate (if required) ... £5:00
 Bill of Lading Expenses, if any, £
 Committee's Minute
 Character assigned
 24th July, 1877.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 © 2021 Lloyd's Register Foundation
 LON662-0222

Mans



© 2021

Lloyd's Register
Foundation