

36,521

REPORT of SURVEY for REPAIRS, &c.

No. in g. Book. **No.** Survey held at *London* Date, first Survey *11 Aug* Last Survey *7 Sept 1877*
on the *"The Goolwa"* Master
TONNAGE under Tonnage Deck *643* Built at *Aberdeen* When built *1864* YEAR. MONTH.
Ditto of Spar Deck, or Avning Deck Owners *A. Lawrence* Port belonging to *London*
Ditto of Poop Residence
Ditto of Raised Qr. Dk. By whom built *Hall* Destined Voyage
Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock *Nelson dry dock & afloat*
Gross Tonnage *718*
Crew Space, as per Rule *718*
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm.
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
Classed *15 A 1 5 76*
P.S. *for 72*
Last Survey, No. Port

REPAIRS, OR EXAMINATION AS PER RULE

This vessel was surveyed with the view to the second S.P., and H.T. survey being carried out. The examination of the hull was completed and all found satisfactory, excepting the floor plates near about main Hatchway aft, some of which were found wasted at the lower part. 10 floor plates in the space referred to, have been doubled with $\frac{9}{16}$ plate, and as the condition of the remainder will not affect the efficiency of the ship for the voyage, it is proposed to defer further repairs until she returns from her present voyage, when the owner as per his letter attached, guarantees to complete the repairs.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Copsides	Ceiling	Cables <i>laid out on deck</i>
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches
Scuppers		

General Observations, Opinion as to Class, &c.

It is submitted that as the owner guarantees to complete the repairs on the ship's return, her class may remain undisturbed in the Register Book.

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ 4 : 4 : } 15 Sep 1877
Certificate (if required) ... £ : :
Travelling Expenses, if any, £)

Committee's Minute 18th September, 1877.

Character assigned

Deferred
the holder

Surveyor to Lloyd's Register of British and Foreign Shipping.



LON662-0284

The Pool was



© 2021

Lloyd's Register
Foundation