

ANNUAL SURVEYS.

36.609

Recd 16.10.77

No. in Reg. Book. on the 391 No. 310 Survey held at London Date, first Survey Oct 10th Last Survey Oct 12th 1877
 Master S. Jenkins
 Tonnage 310 Built at Gloucester When built 1864 - 8
 By whom built Miller Owners W James & Co
 Port belonging to Aberystwyth Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 394 Port of Newport Classed 10A 1 1/2 76
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Y Metal When put on 1876
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition and entitled to remain as classed

Senhouse Martinade

Committee's Minute 10th October, 1877.

Character assigned Good 7A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the 113 No. 462 Survey held at London Date, first Survey Oct 1st Last Survey _____ 1877
 Master _____
 Tonnage 462 Built at Jersey When built 1867
 By whom built Clarke Owners Scrutton Sons & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 33793 Port of London Classed 10A 4 74
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Y Metal When put on 1874
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition & entitled to remain as classed. Capt Campbell was informed that her class was almost run out.

Committee's Minute 10th October, 1877.

Character assigned 10A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

Senhouse Martinade
 Surveyor to Lloyd's Register of British and Foreign Shipping.

