

ANNUAL SURVEYS.

36662

Recd 7. 11. 77- 1877

No. in Reg. Book. 556 No. 154 Survey held at London Date, first Survey 24/10/77 Last Survey 1 Nov Master Price

Tonnage 175 Built at Sunderland When built 1870 2mo
 By whom built Brown Owners Banner Bros
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletchers Dry Dock

Last Survey, No. 36169 Port of London Classed 10 Years assigned 10 Character in Register Book 1

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	H.T. Low <u>75</u>
Waterways <u>do</u>	Breasthooks and Stenson _____	Windlass and Capstan <u>Good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches _____	Pumps <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings _____	Boats <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>where</u>	Masts, Yards, &c. <u>do</u>
Planksheers <u>do</u>	Keelsons _____	Condition, how ascertained <u>From do</u>
Sheerstrakes <u>do</u>	Clamps and Shelves _____	Sails <u>Good</u>
Topsides <u>do</u>	Ceiling <u>seen</u>	Anchors, No. of <u>2B . 1S . 1K</u>
Wales <u>do</u>	Rudder <u>Good</u>	Cables <u>Good</u>
Plank (Bottom) and Counter <u>do</u>	Copper Y.M. over <u>7</u> When put on <u>75</u>	Hawsers and Warps <u>do</u>
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging <u>do</u>
Coal Bunker, Openings, Lids, &c. _____	Scuppers <u>do</u>	Cargo and Main Hatchways <u>Good</u> Hatches <u>do</u>

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 9th November, 1877. J. Hearley
 Character assigned 10 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. 313 No. 52 Survey held at London Date, first Survey 1 Nov 1847 Last Survey 1 Nov Master Barneson

Tonnage 275 Built at Yarmouth When built 1867 5mo
 By whom built Geddie Owners CW + W. Gray
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletchers Dry Dock

Last Survey, No. 1667 Port of Southampton Classed 9 Years assigned 9 Character in Register Book 1

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	Cut Low <u>May 76. 74 (11. 75)</u>
Waterways <u>do</u>	Breasthooks and Stenson _____	Windlass and Capstan <u>Good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches _____	Pumps <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings _____	Boats <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>where</u>	Masts, Yards, &c. <u>do</u>
Planksheers <u>do</u>	Keelsons _____	Condition, how ascertained <u>From Deck</u>
Sheerstrakes <u>do</u>	Clamps and Shelves _____	Sails <u>Good</u>
Topsides <u>do</u>	Ceiling <u>seen</u>	Anchors, No. of <u>3B . 1S . 2K</u>
Wales <u>do</u>	Rudder <u>Good</u>	Cables <u>Good</u>
Plank (Bottom) and Counter <u>do</u>	Copper Y.M. over <u>7</u> When put on <u>75</u>	Hawsers and Warps <u>do</u>
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging <u>do</u>
Coal Bunkers, Openings, Lids, &c. _____	Scuppers <u>do</u>	Cargo and Main Hatchways <u>Good</u> Hatches <u>do</u>

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 9th November, 1877. J. Hearley
 Character assigned Cout 75 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____