

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Oct 1874 Last Survey Nov 15th 1877

1246 on the S Surrey

Master G. James

YEAR.

MONTH.

TONNAGE under Tonnage Deck 958
Ditto of Spar Deck, or Avoning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 1055
Crew Space, as per Rule
Register Tonnage, cut on Beam 1085
Engine Room
Reg. Tons as St'mer, cut on Bm.

Built at Shields

When built 1857

Owners G. Marshall & Co Port belonging to London

Residence

By whom built Marshall

Destined Voyage

If Surveyed Afloat or in Dry Dock Dry Dock Ballast

Length of Poop 130 ft. Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 35771 Port London

Classed

14th 11.76

Cent 1871-74 75 76 77 78 79

REPAIRS, OR EXAMINATION AS PER RULE

At present placed in Dry Dock the yellow metal shipped caulked from keel to gunwale, Waterways & Decks. Iron timber Ports cut forward, a strong additional Iron Breasthook introduced at the lower Port & well through bolted with yellow metal. Part of the Iron Breasthook ^{removed} on the starboard side between Decks in order to cut the Port sufficiently low to receive the timber, and another Breasthook fitted below it.

Re yellow Metalled on jell to load line.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Y Metal When put on Now
on jell to load line
Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3 Iron 18 lbs

Cables

Hawsers and Warps

Standing & Running Rigging

Good & sufficient when

they could be seen

She is now in good condition and entitled to remain as classed.

Senhouse Martindale

The Amount of Entry Fee ... £ ... received by me, J. H.

15/11/77 Special ... £ 2 : 2 : 16 1877

Certificate (if required) ... £ 5

(Travelling Expenses, if any, £ ...)

Committee's Minute

16th November, 1877.

Character assigned

Cont 9

record 9 M.

J. H.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON62-0353