

REPORT of SURVEY for REPAIRS, &c.

Recd 2.3.75

No. in Reg. Book. **No.** Survey held at London Date, first Survey July 18th Last Survey July 24th 1875
71 on the Barque Lady Elizabeth Master E. M. Cobbet
 Tonnage 658 built at Lunderland When built 1869-5 mo
 By whom built Thompson Owners Wilson & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bull Head by Lock & London Docks

Last Survey, No. _____ Port _____

Classed

16

A 1

5.72

REPAIRS, OR EXAMINATION AS PER RULE Damage Repairs from Lie.

Vessel docked on blocks, a portion of the yellow metal sheathing stripped off, and three planks removed from Starboard side Aft. two renewed of Teak and one of American Elm, fastened with yellow metal screw bolts, caulked and sheathed with yellow metal over felt as before.

Cause of Repairs to be clearly stated.

Present Condition of the

Decks	<u>Good</u>	Bolts	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Freemasts	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Condition, how ascertained	<u>"</u>
Planksheers	<u>"</u>	Bitto Bitto at other places	<u>"</u>	Sails	<u>"</u>
Sheerstrakes	<u>"</u>	Keelsons	<u>"</u>	Anchors No. of <u>3 1/2 18-2 K 09</u>	
Topsides	<u>"</u>	Clamps and Shelves	<u>"</u>	Cables	<u>Good</u>
Wales	<u>"</u>	Ceiling	<u>"</u>	Hawsers and Warps	<u>and</u>
Plank (Bottom) and Counter	<u>"</u>	Rudder	<u>"</u>	Standing & Running Rigging	<u>sufficient</u>
Engine Room Skylights	<u>"</u>	Copper <u>Yell. L</u> When put on <u>now</u>		Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Caulking of		Hatches	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>Bottom, Deck, & Waterways</u> <u>Good</u>				

She is now in good and efficient condition and eligible to remain as classed: viz - A 1 for 16 years.

The Amount of Entry Fee ... £ " : : : received by me, }
 Special ... £ 2 : 2 : 187 }
 Certificate (if required) ... £ : : :
 (Travelling Expenses, if any, £ _____)

Committee's Minute _____ 18 _____

Character assigned _____

Thomas W. Blayell
 Will. C. Lavey
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation

LON 662-0450