

# ANNUAL SURVEYS.

37.12.14

No. 8 Survey held at London Date, first Survey 19th Feb Last Survey Red 9.4.78  
 No. in on the 13-15 "Dartmouth" Master Robinson  
 Reg. Book. 91 Tonnage 978 Built at Sunderlee When built 1869-7mo  
 By whom built Stephen Owners Mer. Sh. Co.  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Canal by lock & afloat

Last Survey, No. 36240 Port of London  
 Present Condition of the  
 Decks Good Treenails Good Cont. Lon Jan. 75-10yrs 5-77.  
 Waterways — Breasthooks and Stenson —  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wales — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. on Felt When put on  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom sighted, and the yellow metal Patched.

This Vessel is now in good and efficient condition, and in my opinion eligible to remain as Classed.

Committee's Minute 12th April, 1878.  
 Character assigned Class 10A  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid 18

No. 8 Survey held at London Date, first Survey 21st Feb Last Survey 21st Feb 1878.  
 No. in on the 13-15 "Lennox Castle" Master J. Good  
 Reg. Book. 327 Tonnage 693 Built at Sunderland When built 1865-8mo.  
 By whom built Moore Owners L. Skinner & Co  
 Port belonging to Glasgow Destined Voyage  
 If Surveyed Afloat or in Dry Dock West India by lock.

Last Survey, No. 36329 Port of London  
 Present Condition of the  
 Decks Good Treenails Rivets Good H. T. Ch. 75. 6-77.  
 Waterways — Breasthooks and Stenson — S. S. Ch. 75.  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wales — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. on Felt When put on 1877  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom sighted and the yellow metal sheathing patched.

This Vessel is now in good and efficient condition, and in my opinion eligible to remain as Classed.

Committee's Minute 12th April, 1878.  
 Character assigned Class 14A  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid 18