

# REPORT of SURVEY for REPAIRS, &c.

37251

Rec'd 25.11.76

No. in Reg. Book. **No.** Survey held at *London* Date, first Survey *24 Aug* Last Survey *21 Nov* 18*76*

*129* on the *13<sup>th</sup> Point* Master

TONNAGE under Tonnage Deck *366* Built at *London* When built *1848*

Ditto of Spar Deck, or Aftening Deck Owners *Anderew* Port belonging to *London*

Ditto of Poop Residence

Ditto of Raised Qr. Deck By whom built

Ditto of Houses on Deck Destined Voyage

Ditto of Forecastle If Surveyed Afloat or in Dry Dock *Velson Patent Slip*

Gross Tonnage *366*

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St<sup>r</sup>mer, cut on Bm.

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned *13* Character in Register Book. *Classed 13 Aired 6.74 09 8.8.70-74*

Last Survey, No. *35326* Port *London*

REPAIRS, OR EXAMINATION AS PER RULE *for Half Time*

*Hold cleared. Ristings opened inside at the ends. Bolts and treenails driven out. Windlass unhooked and linings removed. Chain Cables laid out and all other requirements complied with.*

*Repairs owing to defects. A considerable quantity of the Ceiling in turret decks renewed on both sides with Pitch Pine. The frame here repaired, and spars of Hanging Knees introduced in turret decks as additional support to the timbers. Five Hold Beams renewed with Pitch Pine. Three new upper deck Beams P Pine. Caulked from metal to gunwale. Caulking of Bottom tested and found good.*

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		Hatches

General Observations, Opinion as to Class, &c.

*This vessel being in good condition, and the Half Time requirements having been complied with I am of opinion she may remain as classed and H.T. 76 recorded*

The Amount of Entry Fee ... £ *1* : : : received by me, *Thos Congdon*

*15/11/76* Special ... £ *4* : : : 1878

Certificate (if required) ... £ *2* : : :

(Travelling Expenses, if any, £ )

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *11th June 1878*

Character assigned *A1*

*DBM H.T. 76*



© 2021

Lloyd's Register Foundation

LOW663-0042





© 2021

Lloyd's Register  
Foundation