

ANNUAL SURVEYS.

37255
Rec. 3678

No. in Reg. Book. **452** No. **10** Survey held at London Date, first Survey May 10th Last Survey May 28 1878
 on the BK Marina Master J. Jean
 Tonnage 664 Built at Neyland When built 1874 3rd
 By whom built Warlow Owners J. Sheppard & Co
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By Mr. Ballastin

Last Survey, No. 9 Port of Sourabaya Classed 12A 677
Years assigned. Character in Register Book.
 Present Condition of the Decks good Treenails good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan _____
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps _____
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats _____
 Planksheers " Keelsons " Masts, Yards, &c. good &
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained sufficient
 Topsides " Ceiling " Sails where
 Wales " Rudder " Anchors, No. of 3 Br. 11 lb. 10 lb. they
 Plank (Bottom) and Counter " Copper or Y.M. Y Metal When put on 1876 Cables could
 Caulking of Patched new Bottom, Deck, & Waterways good Hawsers and Warps be seen
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition and entitled to remain as classed

Senhouse Martindale

Committee's Minute 7th, June 1878.
 Character assigned 12A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DBW Paid _____ 18 _____

No. in Reg. Book. **556** No. **175** Survey held at London Date, first Survey May 1st Last Survey _____ 1878
 on the Bn Sesame Master H. Price
 Tonnage 175 Built at Sunderland When built 1870 2nd
 By whom built Crown Owners Banner Bes
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By Mr.

Last Survey, No. 36662 Port of London Classed 10A 1077
Years assigned. Character in Register Book.
 Present Condition of the Decks good Treenails good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan _____
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps _____
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats _____
 Planksheers " Keelsons " Masts, Yards, &c. good &
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained sufficient
 Topsides " Ceiling " Sails where
 Wales " Rudder " Anchors, No. of 3 Br. 11 lb. 10 lb. they
 Plank (Bottom) and Counter " Copper or Y.M. Y Metal When put on 1875 Cables could
 Caulking of Patched new Bottom, Deck, & Waterways good Hawsers and Warps be seen
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition and entitled to remain as classed

Senhouse Martindale

Committee's Minute 7th, June 1878.
 Character assigned 10A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DBW Paid _____ 18 _____