

ANNUAL SURVEYS.

37,290

No. Survey held at London Date, first Survey 8 June Last Survey 18
 No. in on the 186 Reg. Book. 137 Tonnage 137 Built at Hayle Master Ellery
 By whom built Harvey Owners A. M. Gillepie & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Princes St dock -

Last Survey, No. 35834 Port of London Classed 11 Years assigned. 4 Character in Register Book. A.1.
 Present Condition of the Decks good Treenails where seen good Cont. Lon July-74 4 10.76
 Waterways so Breasthooks and Stenson so so
 Comings so Transoms, Pointers, and Crutches so so
 Upper Deck Beams & Fastenings so Timbers of the Frame at the Openings so so
 Lower Deck Beams & Fastenings none Ditto ditto at other places not seen
 Planksheers good Keelsons where seen good
 Sheerstrakes so Clamps and Shelves so so
 Topsides so Ceiling so so
 Wales so Rudder so so
 Plank (Bottom) and Counter good Copper or Y.M. good When put on 1876
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers so Cargo and Main Hatchways good Hatches so

General Observations, Opinion as to Class, &c. In dry dock, sighted bottom, patched metal.
Hold ex^d with Cargo therein. Called owner's representative's attention
to the class of the vessel expiring in July next, when he told me that they intended
putting vessel through h-2 for Cont. after next voyage which was short.

Committee's Minute 21st June, 1878. J. Dodd
 Character assigned Class 4A Surveyor to Lloyd's Register of British and Foreign Shipping.
Well Certificate (if required) Paid 18

No. Survey held at London Date, first Survey and Last Survey 12 June 1878
 No. in on the 139 Reg. Book. 483 Tonnage 428 Built at Sunder Master G. Mudie
 By whom built 4683 Sunder Sh. Co Owners W. Thomson
 Port belonging to Sunder Destined Voyage
 If Surveyed Afloat or in Dry Dock Bullhead dry dock

Last Survey, No. 3965 Port of Sunder Classed 11 Years assigned. 4 Character in Register Book. A.1.
 Present Condition of the Decks good Treenails where seen good Cont. 2.76
 Waterways so Breasthooks and Stenson so so
 Comings so Transoms, Pointers, and Crutches so so
 Upper Deck Beams & Fastenings so Timbers of the Frame at the Openings so so
 Lower Deck Beams & Fastenings so Ditto ditto at other places not seen
 Planksheers so Keelsons where seen good
 Sheerstrakes so Clamps and Shelves so so
 Topsides so Ceiling so so
 Wales so Rudder so so
 Plank (Bottom) and Counter so Copper or Y.M. When put on 1876
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers so Cargo and Main Hatchways so Hatches so

General Observations, Opinion as to Class, &c. Vessel in dry dock, metal patched. Hold examined
with Ballast therein. I am of opinion that this vessel
is in a good condition and eligible to remain as
classed in the Register Book.

Committee's Minute 21st June, 1878. J. Dodd
 Character assigned 11A Surveyor to Lloyd's Register of British and Foreign Shipping.
Well Certificate (if required) Paid 18