

ANNUAL SURVEYS.

37.350

No. in Reg. Book. **No.** 283 Survey held at London Date, first Survey 19th June Last Survey 16th July 18 78
 on the Ship "Carnaqueen" Master W. Colville
 Tonnage 826 Built at Aberdeen When built 1867 2nd mo
 By whom built Humphrey Owners Cannon & Co
 Port belonging to Aberdeen Destined Voyage
 If Surveyed ~~Afloat~~ or in Dry Dock Rateliff Dry Dock

Last Survey, No. 36301 Port of London
 Present Condition of the Decks Good Treenails Greenails Good where seen
 Waterways " Breasthooks and Stenson do
 Comings " Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings " Ditto ditto at other places do
 Planksheers " Keelsons do
 Sheerstrakes " Clamps and Shelves do
 Topsides " Ceiling do
 Wales " Rudder good
 Plank (Bottom) and Counter good where seen Copper or Y.M. Y. Mch. When put on 77
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways good
 Coal Bunker, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c.

Bulls of Main Deck caulked. - Renewed 19 bolts, connecting dead eyes to chain plates of Fore & Main Rigging. - Bottom sighted & y. m. sheathing patched. This vessel is now in good, efficient condition & eligible in my opinion to remain as classed. - Surveyed with part of outcargo on board. W. Paulsen.

Committee's Minute 19th July, 1878.

Character assigned Class 3

Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18

No. in Reg. Book. **No.** 1265 Survey held at London Date, first Survey 6th July Last Survey 7th July 18 78
 on the Ship "Pora" Master J. Adams.
 Tonnage 5-61 Built at Workington When built 1859-7 mo
 By whom built Fell Owners J. H. Bushby.
 Port belonging to Workington Destined Voyage
 If Surveyed Afloat or in Dry Dock Linekiln by lock.

Last Survey, No. 36109 Port of London
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. On left When put on 77.
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways Good
 Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted and the yellow metal sheathing patched. This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 19th July, 1878.

Character assigned Class 9

Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18