

REPORT of SURVEY for REPAIRS, &c.

Reid 6.3.79

Survey held at London

Date, first Survey 5 Feb 1879 Last Survey 1 March 1879

on the S. Savoir Faire

Master

YEAR.

MONTH.

1863

16

Built at Liverpool

When built

Owners G. H. Fletcher

Port belonging to Liverpool

Residence

By whom built Royden

Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Net Tonnage under Tonnage Deck 1344

Net Tonnage of Spar Deck, or Awning Deck

Net Tonnage of Poop

Net Tonnage of Raised Qr. Dk.

Net Tonnage of Houses on Deck

Net Tonnage of Forecastle

Net Tonnage of Tonnage

Net Tonnage of Space, as per Rule

Net Tonnage of Register Tonnage, cut on Beam

Net Tonnage of Engine Room

Net Tonnage of Tons as St' mer, cut on Bm.

Net Tonnage of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

First Survey, No.

Port

Classed

S. S. See No 3. 75

4.78

REPAIRS, OR EXAMINATION AS PER RULE

in Annual Survey

Vessel placed in dry dock, her bottom scraped and painted, portions of her topsides chipped where necessary and her rudder painted renewed.

Forecastle deck renewed with $3\frac{1}{2}$ Yellow Pine - The portion of the upper deck between the fore side of main hatchway and the deck house renewed with Yellow Pine. Shing hoops to lower foreyard and 3 boats renewed.

Present Condition of the

Works Part renewed. Good

Waterways Good

Stairways Good

Upper Deck Beams & Fastenings Good

Lower Deck Beams & Fastenings Good

Stanchions Good

Deerstrakes Good

Upsides Good

Scales Good

Plating Good

Bank (Bottom) and Counter Good

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches Good

General Observations, Opinion as to Class, &c.

Freenails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Paint When put on

Caulking of

Bottom, Deck, & Waterways

Good

where

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps

Boats 5 in 10

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3B. 1S. 2K

Cables Good where seen

Hawsers and Warps

Standing & Running Rigging

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

She now appears to be in a good and efficient condition and is eligible in our opinion to remain as classed

The Amount of Entry Fee ... £ ...

6/3/79 Special ... £ 2 : 2 : -

Certificate (if required) ... £ ...

Travelling Expenses, if any, £ ...

Committee's Minute

11th March,

1879.

Character assigned

Good

Good

received by me,

187

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON663-0299