

6/5/79

ANNUAL SURVEYS.

380 PV.

No. Survey held at London Date, first Survey 14th Apr^l Last Survey 17th Apr^l 1879
 No. in on the Barge "Mary" Master L. Alexander.
 Reg. Book. 381 Tonnage 381 Built at Montrose When built 1868 - 7 mo
 By whom built Strachan Owners W. Mitchell
 Port belonging to Montrose Destined Voyage
 If Surveyed Afloat or in Dry Dock Lake shore by dy & afloat

Last Survey, No. 4127 Port of Leith
 Present Condition of the
 Decks Good Treenails Good
 Waterways — Breasthooks and Stemson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons Partly covered with
 Sheerstrakes — Clamps and Shelves Ballast
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. 7 When put on 76
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted yellow metal sheathing patched, Bowsprit and two lower topsail yards new of Pitch Pine.

Classed 9 Years assigned. 9 Character in Register Book. A.1.
 Cont. all 77 3 5-78.
 Windlass and Capstan Good
 Pumps —
 Boats —
 Masts, Yards, &c. —
 Condition, how ascertained Examⁿ
 Sails Good
 Anchors, No. of 3 1/2 15th 2 k eye
 Cables Good
 Hawsers and Warps do.
 Standing and Running Rigging do.

This Vessel is now in good and efficient condition and in my opinion eligible to remain as Classed

Committee's Minute 9th May, 1879.

Character assigned Classed 3A

Thos Wm Blayell.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

TRW Certificate (if required) Paid 18

No. Survey held at London Date, first Survey 23rd Apr^l Last Survey 6th May 1879
 No. in on the Barge "Ethel" Master A. Ross.
 Reg. Book. 556 Tonnage 556 Built at Sunderland When built 1866 - 3 mo.
 By whom built 496 Pile Owners Fennell & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Union by lock & afloat.

Last Survey, No. 34285 Port of London
 Present Condition of the
 Decks Good Treenails Bolts Good
 Waterways — Breasthooks and Stemson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. 7 When put on 77
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom examined and the yellow metal sheathing patched.

Classed 14 Years assigned. 14 Character in Register Book. A.1.
S. A. Lin. 77. 6.78
H. T. Lin. 773
 Windlass and Capstan Good
 Pumps —
 Boats —
 Masts, Yards, &c. —
 Condition, how ascertained Furn bell
 Sails Good
 Anchors, No. of 3 1/2 15th 2 k eye
 Cables Good
 Hawsers and Warps do.
 Standing and Running Rigging do.

This Vessel is now in good and efficient condition and in my opinion eligible to remain as Classed.

Committee's Minute 9th May, 1879.

Character assigned Classed 14A

Thos Wm Blayell.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

TRW Certificate (if required) Paid 18