

REPORT of SURVEY for REPAIRS, &c.

No. 23564 38137 (Paid 23.5.79)
 No. in Reg. Book. 549 on the Barque Durban Survey held at London Date, first Survey 8 May/79 Last Survey 21 May 1879
 Master Newton

TONNAGE under Tonnage Deck 275
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 345
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 332
 Engine Room
 Reg. Tons as St'mer, cut on Bm.
 Built at London When built 1870 YEAR. MONTH. 3
 Owners Bullard King & Co Port belonging to London
 Residence
 By whom built Salisbury Destined Voyage Port Natal
 If Surveyed Afloat or in Dry Dock Afloat in S.E. Katherine's Docks

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 10 Character in Register Book. A 1
 Last Survey, No. 34559 Port London Classed 10 1078

REPAIRS, OR EXAMINATION AS PER RULE on Annual Survey H.T. 2m. 75

Vessel surveyed afloat with outward cargo covering flat of ceiling.
 Main Mast - Main Yard - and Mizzen topmast renewed with R. Pine - also main topgall⁵ mast renewed with Rija Fir.
 A bower anchor and 45 fathoms of chain cable now supplied - as follows:-
 1 Bower Anchor - No 4642 - Weight $\frac{1}{2}$ 3. 0. 12 - Test 15. 1. 2. 7 - Lipton P.H. 8 May 1879 (Signed) E. R. Scott.
 45 Fms chain cable. $\frac{1}{4}$ - No 4259 - Tensile strain - 288 - Breaking lbs 428 - Lipton P.H. 8 May 1879 (Signed) E. R. Scott.

Present Condition of the					
Decks	Good	Treenails	not exam ^d	Windlass and Capstan	Good
Waterways	do	Breasthooks and Stemson	Good	Pumps	do
Comings	do	Transoms, Pointers, and Crutches	do	Boats	do
Upper Deck Beams & Fastenings	do	Timbers of the Frame at the openings	do	Masts, Yards, &c.	do
Lower Deck Beams & Fastenings	do	Ditto Ditto at other places	not seen	Condition, how ascertained	Aloft
Planksheers	do	Keelsons	do	Sails	Good
Sheerstrakes	do	Clamps and Shelves	Good	Anchors No. of	3 B. 15. 2 K
Topsides	do	Ceiling	Part seen - do	Cables	Part seen - Good
Wales	do	Rudder	Good	Hawsers and Warps	Supplied - do
Plank (Bottom) and Counter	not seen	Copper Yellow When put on	1878	Standing & Running Rigging	Good
Engine Room Skylights		Caulking of		Cargo and Main Hatchways	Good
	Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Good	Hatches	do
		Scuppers	do		

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed

The Amount of Entry Fee ... £ ... received by me, 26/5/79 Special ... £ ... 29 May 1879
 Certificate (if required) ... £ ...
 (Travelling Expenses, if any, £ ...)
 Committee's Minute 27th May, 1879.
 Character assigned 10 A
213W

J. Shearke
 Surveyor to Lloyd's Register of British and Foreign Shipping.



LON663-0380