

# ANNUAL SURVEYS.

38331

No. \_\_\_\_\_ Survey held at London Date, first Survey 18 July 79 Last Survey 23 July 1879  
 No. in on the B<sup>re</sup> Cymbeline Master Vigot  
 Reg. Book. 391 Tonnage 391 Built at Bridport When built 1863 3 mo  
1540 By whom built Cox Owners Smart & Simpson  
 Port belonging to London Destined Voyage Demerara  
 If Surveyed Afloat or in Dry Dock Linckilin Dry Dock

Last Survey, No. 36946 Port of London Classed 14 Years assigned. 14 Character in Register Book. 1  
 Present Condition of the Decks Good Treenails Good but low 77 - 9 yrs.  
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good  
 Comings do Transoms, Pointers, and Crutches do Pumps do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. do  
 Planksheers do Keelsons do Condition, how ascertained From aloft  
 Sheerstrakes do Clamps and Shelves do Sails Good  
 Topsides do Ceiling do Anchors, No. of 3B . 1S . 2K  
 Wales do Rudder do Cables Part seen Good  
 Plank (Bottom) and Counter do Copper or Y.M. Cement When put on 63 Hawsers and Warps do  
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging do  
 Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do

General Observations, Opinion as to Class, &c. She is now in a good condition and is eligible in my opinion to remain as classed.

Committee's Minute 5th August, 1879 J. Hearle  
 Character assigned Class 9 A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) JBW Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at London Date, first Survey 24 July 79 Last Survey 25 July 1879  
 No. in on the S<sup>r</sup> Sam Weller Master S. Down  
 Reg. Book. 148 Tonnage 177 Built at Brischam When built 1864 7 mo  
148 By whom built Apham Owners P. Parrell & Co  
 Port belonging to Brischam Destined Voyage Bermuda  
 If Surveyed Afloat or in Dry Dock Afloat in W. India Sts

Last Survey, No. 7474 Port of Greenock Classed 12 Years assigned. 12 Character in Register Book. 1  
 Present Condition of the Decks Good Treenails Good but low July 76 - 8 yrs - 678  
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good  
 Comings do Transoms, Pointers, and Crutches do Pumps do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. do  
 Planksheers do Keelsons do Condition, how ascertained Aloft  
 Sheerstrakes do Clamps and Shelves do Sails Good  
 Topsides do Ceiling do Anchors, No. of 2B . 1S . 1K  
 Wales do Rudder do Cables Part seen Good  
 Plank (Bottom) and Counter do Copper or Y.M. cement When put on 76 Hawsers and Warps do  
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging do  
 Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do

General Observations, Opinion as to Class, &c. Vessel surveyed afloat. A clasp hoop fitted to fore mast, under rubby piece to jaff.  
She is now in a good condition and eligible in my opinion to remain as classed.

Committee's Minute 5th August, 1879 J. Hearle  
 Character assigned Class 9 A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) JBW Paid \_\_\_\_\_ 18 \_\_\_\_\_

