

# ANNUAL SURVEYS.

38505

No. 2505 Survey held at London Date, first Survey 13 Sept. Last Survey 15 Sept 1879  
 No. in on the Bk "Mary Ann Holman" Master J. Roach  
 Reg. Book. 622 Tonnage 272/- Built at Topham When built 1859 - 10 mo.  
 By whom built Holman Owners John Holman & Son  
 Port belonging to Exeter Destined Voyage not fixed  
 If Surveyed Afloat or in Dry Dock Nelson Slipway

Last Survey, No. 2960 Port of Plymouth Classed 14 Years assigned. 14 Character in Register Book. A1  
 Present Condition of the Decks Good Treenails Good Cont. Ips. June 74/9 7.77  
 Waterways do Breasthooks and Stenson do H.T. Ips. 77  
 Comings do Transoms, Pointers, and Crutches do Windlass and Capstan Good  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places not seen Boats do  
 Planksheers do Keelsons Good Masts, Yards, &c. do  
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from D's Enquiry  
 Topsides do Ceiling do Sails Well found  
 Wales do Rudder do Anchors, No. of 3B, 15, 2H.  
 Plank (Bottom) and Counter do Copper or Y.M. on felt When put on '76 Cables Complete  
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers do Hawers and Warps Good & sufficient  
 General Observations, Opinion as to Class, &c. Good Standing and Running Rigging Good  
 Cargo and Main Hatchways Good Hatches do

The bottom sighted and about 100 sheets of metal renewed. This vessel appears to be now in good condition, and eligible in my opinion to remain as at present classed.

Committee's Minute 26th September, 1879. Edwards.  
 Character assigned Good 7A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid 18

No. 249 Survey held at London Date, first Survey 16 Sept. Last Survey 16 Sept. 1879  
 No. in on the Bk "Helen" Master John Legoe  
 Reg. Book. 249 Tonnage 378/- Built at Sunderland When built 1862 - 9 mo.  
 By whom built Mills Owners Thomson Hankey & Co.  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Nelson Slipway

Last Survey, No. 36659 Port of London Classed 11 Years assigned. 11 Character in Register Book. A1  
 Present Condition of the Decks Good Treenails Good Cont. Lon June 74 10.77  
 Waterways do Breasthooks and Stenson do H.T. Lon 77  
 Comings do Transoms, Pointers, and Crutches do Windlass and Capstan Good  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Pumps do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places not seen Boats 3n  
 Planksheers do Keelsons Good Masts, Yards, &c. do  
 Sheerstrakes do Clamps and Shelves do Condition, how ascertained from D's Enquiry  
 Topsides do Ceiling do Sails Well found  
 Wales do Rudder do Anchors, No. of 3B, 15, 2H.  
 Plank (Bottom) and Counter do Copper or Y.M. on felt When put on '77 Cables Complete  
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers do Hawers and Warps Good & sufficient  
 General Observations, Opinion as to Class, &c. Good Standing and Running Rigging Good  
 Cargo and Main Hatchways Good Hatches do

Surveyed with ballast in hold amidships and abaft Mizzen Mast. The Bottom sighted and metal sheathing patched where required. This vessel appears to be now in good condition and eligible in my opinion to remain as at present classed.

Committee's Minute 26th September, 1879. Edwards.  
 Character assigned Good 7A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid 18