

ANNUAL SURVEYS.

38412

No. 28412 Survey held at London Date, first Survey 22 Nov^r 79 Last Survey 10 December 1879
 No. in on the Bk Cornwallis Master J. W. Baker
 Reg. Book. 1315 Tonnage 410 Built at Marport When built 1862 1 m.
 By whom built Riton Owners A. B. Poulsonby
 Port belonging to Plymouth Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock

Last Survey, No. 38645 Port of London
 Present Condition of the
 Decks Good Treenails Good but dw. 77. 10 yrs 8.77
 Waterways dr Breasthooks and Stemson dr
 Comings dr Transoms, Pointers, and Crutches dr
 Upper Deck Beams & Fastenings dr Timbers of the Frame at the Openings dr
 Lower Deck Beams & Fastenings dr Ditto ditto at other places dr
 Planksheers dr Keelsons dr
 Sheerstrakes dr Clamps and Shelves dr
 Topsides dr Ceiling dr
 Wales dr Rudder dr
 Plank (Bottom) and Counter dr Copper or Y.M. over 7 When put on 77
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers dr Cargo and Main Hatchways dr Hatches dr
 General Observations, Opinion as to Class, &c. Vessel placed in dry dock and her yellow metal sheathing patched. Foreyard and mainmast renewed. She is now in a good condition and eligible in my opinion to remain as classed. This vessel's port of register has been altered since last surveyed.
 Committee's Minute 12th December, 1879.
 Character assigned Class 10A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 313 Survey held at London Date, first Survey 1 Dec^r 79 Last Survey 3 December 1879
 No. in on the Bkn. Satellite Master Winter
 Reg. Book. 313 Tonnage 275 Built at Harwich When built 1864 5 m.
 By whom built Liddle Owners C. W. & W. Gray
 Port belonging to London Destined Voyage Bermuda
 If Surveyed Afloat or in Dry Dock N. India etc. Afloat
 Last Survey, No. 34031 Port of London
 Present Condition of the
 Decks Good Treenails Good but dw. May 76. 7 yrs. 12.77
 Waterways dr Breasthooks and Stemson dr
 Comings dr Transoms, Pointers, and Crutches dr
 Upper Deck Beams & Fastenings dr Timbers of the Frame at the Openings dr
 Lower Deck Beams & Fastenings dr Ditto ditto at other places dr
 Planksheers dr Keelsons dr
 Sheerstrakes dr Clamps and Shelves dr
 Topsides dr Ceiling dr
 Wales dr Rudder dr
 Plank (Bottom) and Counter dr Copper or Y.M. over 7 When put on 77
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers dr Cargo and Main Hatchways dr Hatches dr
 General Observations, Opinion as to Class, &c. Vessel surveyed afloat. She is now in a good and efficient condition and eligible in my opinion to remain as classed.
 Committee's Minute 12th December, 1879.
 Character assigned Class 10A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18