

# REPORT of SURVEY for REPAIRS, &c.

No. 38926

(Received at London Office 24.2.80)

No. in Survey held at London Date, first Survey 12 Feb Last Survey 23 February 1880

1046 on the "Michael Angelo" Master A. M. Groussard

TONNAGE under Tonnage Deck 1085  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 1174  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm.  
 Built at Glasgow When built 1865  
 Owners J. Hiddett & Sons Port belonging to London  
 Residence  
 By whom built Bouquet Destined Voyage Alga Bay  
 If Surveyed Afloat or in Dry Dock Barter's dry dock  
 (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 16 Character in Register Book. M 4 78

Last Survey, No. 349 Port Glas. Classed 16 M 4 78

REPAIRS, OR EXAMINATION AS PER RULE and improved class  
 Cause of Repairs to be clearly stated.

Yellow Metal stripped off and the bottom cleaned down.  
The iron bolts of upper Black Waterway which passed through  
the stanchions and sheerstrake, were found wasted. These  
bolts have now been renewed with Y. metal from poop  
to forecastle. Caulked from keel to foremast and  
reketatted over felt as before.  
The side planking of poop and forecastle is now fastened.

The case of this Vessel, as regards the raised class, has  
already received the attention of the Committee, and the  
owner informed by letter from Sect<sup>y</sup> of 9<sup>th</sup> Feb/80 that she would  
be eligible to be classed 19 A. w. 16 yr Table I  
3. fastenings

## Present Condition of the

Decks	Good	Treeails/Bolts	Good	Windlass and Capstan	Good
Waterways	d <sup>c</sup>	Breasthooks and Stemson	d <sup>c</sup>	Pumps	two d <sup>c</sup>
Comings	d <sup>c</sup>	Transoms, Pointers, and Crutches	d <sup>c</sup>	Boats	four d <sup>c</sup>
Upper Deck Beams & Fastenings	d <sup>c</sup>	Timbers of the Frame at the openings	d <sup>c</sup>	Masts, Yards, &c.	d <sup>c</sup>
Lower Deck Beams & Fastenings	d <sup>c</sup>	Ditto Ditto at other places	d <sup>c</sup>	Condition, how ascertained from deck	
Planksheers	d <sup>c</sup>	Keelsons	d <sup>c</sup>	Sails	well found
Sheerstrakes	d <sup>c</sup>	Clamps and Shelves	d <sup>c</sup>	Anchors No. of	30. 1 S & 2 Kedges
Topsides	d <sup>c</sup>	Ceiling	d <sup>c</sup>	Cables	complete
Wales	d <sup>c</sup>	Rudder	d <sup>c</sup>	Hawsers and Warps	sufficient
Plank (Bottom) and Counter	d <sup>c</sup>	Copper (or Y.M.) <u>Y. M.</u> When put over <u>Feb/80</u>		Standing & Running Riggings	good
Engine Room Skylights		Caulking of <u>infelt</u>		Cargo and Main Hatchways	d <sup>c</sup>
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	d <sup>c</sup>	Hatches	d <sup>c</sup>
		Coal Bunker, Openings, Lids, &c.			
		Scuppers	d <sup>c</sup>		

This Vessel is now in good condition and entitled  
to be classed 19 A. as above. 16 yr Table I with the notation in  
the Register Book, as in similar 19 cases of gal. iron above upper deck.  
3. fastenings

The Amount of Entry Fee ... £ : : :  
25/4/80 Special ... £ : : :  
 Certificate (if required)  
 to be sent as per margin... £ : 5 :

(Travelling Expenses, if any, £)

Committee's Minute 26<sup>th</sup> Feb 18 80

Character assigned Raised to 19 A. 1  
C.F. 9. I.B. above upper deck

Surveyor to Lloyd's Register of British and Foreign Shipping



Lloyd's Register  
 Foundation



Michael Hopps



© 2021

Lloyd's Register  
Foundation