

38944

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 17.3.80)

No. 38944

No. in Survey held at London

Date, first Survey 12th March Last Survey 12th March 1880

Reg. Book.

558 on the Br. "Sesame"

Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck 182

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage 187

Crew Space, as per Rule

Register Tonnage, cut on Beam 175

Engine Room

Reg. Tons as St'mer, cut on Bm.

Built at Sunderland

When built 1870

Owners Bengel Bros.

Port belonging to London

Residence Whitstable

By whom built Crown

Destined Voyage

Is Surveyed Afloat or in Dry Dock Vetchers Union Dry Dock

(State Name of Dock)

Length of Poop ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

Classed 10

Character in Register Book.

Last Survey, No. 37651

Port Lon.

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

H. G. Lon. 75

Change of Owners.

Visited the vessel & sighted bottom, but had no opportunity to examine other parts of her.

It was intimated to the owner that a survey should now be held on the vessel, to which he stated in reply, that the classification of the vessel is intended to be discontinued.

Owners letter attached herewith.

H. Paulson

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Y.M.)

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

The Amount of Entry Fee ... £ : : received by me, }

Special ... £ : : 18 }

Certificate (if required) } £ : :
to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Friday, March, 19th 1880

Character assigned

To be Marked Expired

TJW

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation