

REPORT of SURVEY for REPAIRS, &c.

39040 13

No. 39040 (Received at London Office, 2-4-80)
 No. in Survey held at London Date, first Survey and Last Survey 30th Mar 1880
 Reg. Book. 740 on the Bk "Lota" Master W. Dudgefield
 TONNAGE under Tonnage Deck 447 YEAR. MONTH. 1861
 Ditto of Spar Deck, or Awning Deck Built at Liverpool When built
 Ditto of Poop Owners W. M. & J. O. Dudgefield Port belonging to London
 Ditto of Raised Qr. Dk. Residence Southern
 Ditto of Houses on Deck By whom built Lota Destined Voyage Not fixed
 Ditto of Forecastle Gross Tonnage 472
 Crew Space, as per Rule Register Tonnage, cut on Beam 472
 Engine Room If Surveyed Afloat or in Dry Dock Afloat London Dock
 Reg. Tons as St' mer, cut on Bm. (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 106 Port S. K. Classed 13 A 1 3.79
 REPAIRS, OR EXAMINATION AS PER RULE Cont. Pad June 75-4 20p 2
 Cause of Repairs to be clearly stated. omitted

*Preliminary Survey held with a view to continuation under 2nd part of Rule Sec 54
 Stays made at Toppide height, a good many Treennails driven out. Some found defective and others broken. Examined frame in the Treennail holes and found some defective in way of Roe and Main chains - such on the Port side only. Starboard side not examined. The owner electing not to proceed any further with the survey*

Wm^r C. Davy

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper (or Y.M.) When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	
Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
Hatches		

General Observations, Opinion as to Class, &c.


The Amount of Entry Fee £ : : received by me, }
 Special £ 1 : 1 : 18

Certificate (if required) to be sent as per margin... } £ : :
 Travelling Expenses, if any, £)

Committee's Minute Tuesday, April 6th 1880.

Character assigned Insert black line
TJW 3, 80

Surveyor to Lloyd's Register of British and Foreign Shipping.



LON664-0226