

REPORT of SURVEY for REPAIRS, &c.

39534

(Received at London Office, 26. 8. 80)

No. 39534
 No. in Survey held at Reg. Book. 663 on the Sr "Royal Eagle"
 Date, first Survey 5th Aug Last Survey 7th Aug 1880
 Master Lewis
 Tonnage under Tonnage Deck 120
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 120
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 120
 Engine Room
 Reg. Tons as St' mer, cut on Bm.

Built at Littlehampton When built 1824
 Owners E. Allen Port belonging to London
 Residence
 By whom built
 Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Fountain dry Dock
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Years assigned 12 Character in Register Book A.1

Last Survey, No. 36838 Port London
 REPAIRS, OR EXAMINATION AS PER RULE Re-Entry in the Register
 Cause of Repairs to be clearly stated.

Vessel placed in dry dock, bottom cleaned, and caulked from keel to gunwale - a few keel bolts retightened.

Present Condition of the	Good	Treenails	Good	Windlass and Capstan	Good
Decks	Good	Breasthooks and Stenson	Good	Pumps	Good
Waterways	"	Transoms, Pointers, and Crutches	"	Boats <u>2 in No.</u>	"
Comings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained <u>from deck</u>	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails <u>sufficient</u>	"
Planksheers	"	Clamps and Shelves	"	Anchors <u>No. of 2 B. 15 & 1 K</u>	"
Sheerstrakes	"	Ceiling	"	Cables <u>part seen</u>	"
Topsides	"	Rudder	"	Hawsers and Warps <u>sufficient</u>	"
Wales	"	Copper (or Y.M.) <u>Lar</u> When put on <u>new</u>	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Caulking of Bottom, Deck, & Waterways	"		"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	"	Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches	"

General Observations, Opinion as to Class, &c.
This vessel is now in good condition, and in my opinion eligible to be re-entered in the Register.

The Amount of Entry Fee ... £ : 10 : 0 } received by me, [Signature]
 Special ... £ : 1 : 0 }
 Certificate (if required) to be sent as per margin... }
 (Travelling Expenses, if any, £)

R. Williamson
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute Friday, August 27th, 1880
 Character assigned A. 1

[Form No. 2 for Repairs.—4,000—10/5/80.]

[Insert Character precisely as in Register Book.]

