

## ANNUAL SURVEYS.

39701

No. 39701 Survey held at London Date, first Survey 25th Sep Last Survey 25th Sep 1880  
No. in on the 199 B<sup>d</sup> "Minalto" Master Marr  
Reg. Book. 1081 Tonnage 215 Built at Scilly When built 1861 - 5M  
By whom built Mumford Owners A. Marr  
Port belonging to London Destined Voyage St Vincent  
If Surveyed Afloat or in Dry Dock Shadwell Basin

Last Survey, No. 3490 Port of Bristol  
Present Condition of the  
Decks Good Treenails Good  
Waterways do Breasthooks and Stemson do  
Comings do Transoms, Pointers, and Crutches do  
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
Lower Deck Beams & Fastenings do Ditto ditto at other places do  
Planksheers do Keelsons do  
Sheerstrakes do Clamps and Shelves do  
Topsides do Ceiling do  
Wales do Rudder do  
Plank (Bottom) and Counter do Copper or Y.M. do When put on 1848  
Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches do  
General Observations, Opinion as to Class, &c. —

Classed 10 A1 Red  
Years assigned. 07 10-78  
Character in Register Book. S.P. 78-3 yrs

*This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.*

Committee's Minute

Friday, October 15th 1880

Character assigned

A1  
TRWR. Williamson

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) — Paid — 18 —

No. — Survey held at London Date, first Survey 4th Sep Last Survey 10th Sep 1880  
No. in on the 465 S. "Jubilee" Master not appointed  
Reg. Book. 540 Tonnage 765 Built at Warrington When built 1854  
By whom built 739 Owners J. Brodie & Co.  
Port belonging to London Destined Voyage not fixed  
If Surveyed Afloat or in Dry Dock Princes dry dock

Last Survey, No. 132 Port of Man  
Present Condition of the  
Decks Good Treenails Good  
Waterways do Breasthooks and Stemson do  
Comings do Transoms, Pointers, and Crutches do  
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
Lower Deck Beams & Fastenings do Ditto ditto at other places do  
Planksheers do Keelsons do  
Sheerstrakes do Clamps and Shelves do  
Topsides do Ceiling do  
Wales do Rudder do  
Plank (Bottom) and Counter do Copper or Y.M. do When put on 1844  
Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches do  
General Observations, Opinion as to Class, &c. —

Classed 14 A1  
Years assigned. 09 4-49  
Character in Register Book. Cont Lon-71  
H.T. Hul 78 Class will  
Expire on 8/12/80

*Yellow metal sheathing patched, but much worn and not fit for another voyage, submitted to the executors of the late Owner the desirability of stripping yellow metal & caulking bottom, when the preliminary survey could be made for reclassing, but as the vessel was for sale, such was declined.*

*We are of opinion she may continue as classed until Dec<sup>r</sup> next*

Committee's Minute

Friday, October 15th 1880

Character assigned

Cup 9A  
TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) — Paid — 18 —