

REPORT of SURVEY for REPAIRS, &c.

No. 39796

No. in Survey held at Reg. Book.

London

Date, first Survey 24th Oct - Last Survey 11th Nov 1880

11 on the

S. 'Camara'

Master Henry Wight

TONNAGE under Tonnage Deck 1166
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 1364
Crew Space, as per Rule
Register Tonnage, cut on Beam 1306
Engine Room
Reg. Tons as St mer, cut on Bm.

Built at Greenock When built 1874
Owners Albion Shipping Co Port belonging to Glasgow
Residence
By whom built Scott
Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Limehouse Dry Dock
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 25094 Port Inver S.S. Cly. No 1 78 11. 79
REPAIRS, OR EXAMINATION AS PER RULE
Cause of Repairs to be clearly stated.

On the last outward voyage of this vessel to New Zealand a little cargo was reported to have been slightly damaged under the Galley & Front of poop: while in the above port the Galley & donkey boiler house floors were removed, the deck recaulked & re-cemented before replacing the tiles; the W.C's in Front of poop were refitted, & poop & deck house sills re-caulked; this seems to have been efficiently done, as there are no signs of further leakage, & the vessel has turned out her cargo in good condition: She has been examined in Dry Dock, timbers lifted and the bottom cleaned & coated.

Present Condition of the

Decks	Good	Freenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps Complete &	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats 6 in. No	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained from Deck	"
Planksheers	"	Keelsons	"	"	Sails 2 suits & Good	"
Sheerstrakes	Plating	Clamps and Shelves	"	"	Anchors No. of 3 B. 1 S. 2 H.	"
Topsides	"	Ceiling	"	"	Cables Complete & Good	"
Wales	"	Rudder	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or Y.M.) Coating When put on	"	"	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of Bottom, Deck, & Waterways	"	Good	Cargo and Main Hatchways	Good Hatches - "
Coal Bunker, Openings, Lids, &c.	"	Scuppers	"	"		

General Observations, Opinion as to Class, &c.

She is now in good and efficient condition and eligible, in my opinion, to continue as classed

The Amount of Entry Fee ... £ 1 : 1 : 0 received by me, }
15/11/80 Special ... £ 1 : 1 : 0 14/1881 }
Certificate (if required) } £ : 5 :
to be sent as per margin... }

(Travelling Expenses, if any, £)

Committee's Minute

Tuesday, November, 16th 1880.

Character assigned

100 A 1

James Surpin
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON664-0508