

Report of Survey for Repairs of Engines and Boilers.

No.

No. in Reg. Book.

Survey held at

Date, first Survey

Last Survey

1880

387

on the Machinery of the

S.S. "Libra"

(Number of Visits

2

Year

Tonnage, Gross

1030

Built at

Dundee

When built

1869

Ditto, Net

917

Owners

Gen. Stm. Nav. Co.

Port belonging to

London

Diameter of Cylinder

43 + 78

Engines made by

Gourlay

When made

1869

1876

Length of Stroke

36"

Boilers made by

R. & M. Eng. Co.

When made

1876

Pressure of Steam

65 lb.

If Surveyed Afloat or in Dry Dock

Dry Dock

Classed

Years assigned.

Character in Register Book.

Registered Horse Power

250

+

Lloyd's M.C. 2.80

Last Survey No.

Port

Particulars of Repairs and Examination For Annual Survey -
Vessel placed in dry dock, sea connections examined and found to be in good condition. Propeller and its connections in good condition. Crank shaft found to be flawed, A new crank shaft has been fitted.

General Observations, Opinion, and Recommendation :— As far as seen this ship appears eligible to remain as classed.

Entry or Registering Fee

...

£

:

:

Survey Fee

...

£

:

—

Certificate (if required)

...

£

:

:

received by me,

188

(Travelling Expenses, if any, £)


Committee's Minute

Assigned

Friday, December 3rd. 1880,

Geo. E. Wilkinson

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



(Condition of Engines and ...)

(Insert Character precisely as in the Register Book.)

It is submitted that
this vessel is
eligible to remain
as classed

JM.
31/11/80

