

ANNUAL SURVEYS.

No. *3874* Survey held at *London* Date, first Survey *and* Last Survey *23rd Dec^r* 1880
 No. in on the *Bk "Kentish Lass"* Master *H Gray*
 Reg. Book. *110* Tonnage *306.316.271* Built at *Bideford* When built *1872 - 11 mo*
 By whom built *Lox* Owners *R & A Swaway*
 Port belonging to *London* Destined Voyage *Panama*
 If Surveyed Afloat or in Dry Dock *Globe dry Dk*

Last Survey, No. *3874* Port of *Iron* Classed *15* Years assigned. *A 1* Character in Register Book. *9.79*
 Present Condition of the Decks *Good* Treenails *Good*
 Waterways *---* Breasthooks and Stemson *---*
 Comings *---* Transoms, Pointers, and Crutches *---*
 Upper Deck Beams & Fastenings *---* Timbers of the Frame at the Openings *---*
 Lower Deck Beams & Fastenings *---* Ditto ditto at other places *not seen*
 Planksheers *---* Keelsons *Good*
 Sheerstrakes *---* Clamps and Shelves *---*
 Topsides *---* Ceiling *---*
 Wales *---* Rudder *---*
 Plank (Bottom) and Counter *not seen* Copper or Y.M. or f. When put on *1878*
 Engine Room Skylights *---* Coal Bunker, Openings, Lids, &c. *---* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*
 General Observations, Opinion as to Class, &c.

Docked to sight bottom. drew owners' attention to the half time survey now due, informed by them of being permitted by application to the Secretary to postpone such until July next. - She is where seen in good condition and in my opinion eligible to continue as classed

Committee's Minute *Friday, December 16th 1880.*

Character assigned *15 A 1*

Will. C. Davey
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) *---* Paid *---* 18 *---*

No. *338* Survey held at *London* Date, first Survey *19th Nov^r* Last Survey *3rd Dec^r* 1880
 No. in on the *Bk "Scops"* Master *H. Burgess*
 Reg. Book. *338* Tonnage *38.377.327* Built at *Littlehampton* When built *1876. 7 mo*
 By whom built *Harvey* Owners *A & M. Lister*
 Port belonging to *London* Destined Voyage *Katal*
 If Surveyed Afloat or in Dry Dock *Wilson dry Dock & afloat*

Last Survey, No. *34904* Port of *Iron* Classed *12* Years assigned. *A 1* Character in Register Book. *3.79*
 Present Condition of the Decks *Good* Treenails *Good*
 Waterways *---* Breasthooks and Stemson *---*
 Comings *---* Transoms, Pointers, and Crutches *---*
 Upper Deck Beams & Fastenings *---* Timbers of the Frame at the Openings *---*
 Lower Deck Beams & Fastenings *---* Ditto ditto at other places *not seen*
 Planksheers *---* Keelsons *Good*
 Sheerstrakes *---* Clamps and Shelves *---*
 Topsides *---* Ceiling *---*
 Wales *---* Rudder *---*
 Plank (Bottom) and Counter *not seen* Copper or Y.M. *ATYK* When put on *1879*
 Engine Room Skylights *---* Coal Bunkers, Openings, Lids, &c. *---* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*
 General Observations, Opinion as to Class, &c.

Yellow metal patched. 13. Yellow metal bolts renewed in Hold Beam Riders. she appears firm and good and in my opinion eligible to continue as classed

Committee's Minute *Friday, December 16th 1880.*

Character assigned *12 A 1*

Will. C. Davey
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) *---* Paid *---* 18 *---*