

ANNUAL SURVEYS.

No. 39984 Survey held at London Date, first Survey Dec 17th Last Survey Dec 30th 1880
No. in on the S Oriflamme Master W burphey
Reg. Book. 243 Tonnage 1418 Built at Liverpool When built 1865-3
By whom built Heart Owners E Bates & Sons
Port belonging to Liverpool Destined Voyage San Francisco
If Surveyed Afloat or in Dry Dock Penton Victoria Dock

Last Survey, No. 21893 Port of Iron Classed A1 1. 9. 78.
Present Condition of the Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stenson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Canted When put on new
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c. Bottom &c canted

She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, January 14th, 1881. Senhouse Martindale
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) TRW Paid 18

No. 25034 Survey held at London Date, first Survey Dec 8th Last Survey Dec 23rd 1880
No. in on the S Saint Mildred Master J O Murray
Reg. Book. 91 Tonnage 1363 Built at Stockton When built 1877
By whom built Richardson Owners Rankin Gilmore & Co.
Port belonging to Glasgow Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Penton Victoria Dock

Last Survey, No. 25034 Port of Iron Classed 100A 11. 79.
Present Condition of the Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stenson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Canted When put on new
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c. Bottom &c canted

She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, January 14th, 1881. Senhouse Martindale
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) TRW Paid 18

1. *Correspondence:* Dr. J. A. J. van't Hof, Department of Infectious Diseases, University Hospital Groningen, P.O. Box 30.001, 3000 RB Groningen, The Netherlands. Tel: +31 (0) 931 206100; Fax: +31 (0) 931 206101; E-mail: j.a.j.van't.hof@azg.umcg.nl

Lloyd's Register
Foundation