

ANNUAL SURVEYS.

39985

(Received at London Office)

No. 39985 Survey held at London Date, first Survey Dec 31/80 Last Survey Jan 7 1881
 No. in on the S.S. Hankow Master Symington
 Reg. Book. 51 Tonnage 3594 Built at Newcastle When built 1873-10
 By whom built Mitchell Owners W. Milburn & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Royal Albert by the Afloat

Last Survey, No. 27774 Port of London Classed 100 A 8.80
 Present Condition of the Decks Good Treenails Revised Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Plank sheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Good When put on Good
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Bottom & counter, a Bower anchor now supplied.
39-3-2 tested to 36 Jan 13-7-21 Netherston Testing House dated Dec 23-1880. Signed J. Lewis
Also now supplied 30 fathoms of 2 3/4 Chain cable tested to 86 fms 2-2-81. Breaking strain 120 1/2 fms
Netherston Testing House dated Dec 22-1880. Signed J. Lewis.
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, January 14th. 18 81. Senhouse Mastin
 Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Plank sheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____

