

# ANNUAL SURVEYS.

40138

No.            Survey held at London Date, first Survey Juny 21<sup>st</sup> Last Survey Feb 28<sup>th</sup> 18 81  
 No. in on the S S Thames Master Emerson  
 Reg. Book. 181 Net 1057 Built at Dumbarton When built 1871 3  
 Tonnage { Gross 1687 By whom built M. Millar Owners Temperleys Carter & Burke  
 Under Dk. 1657 Port belonging to London Destined Voyage Cape  
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock  
 (State Name of Dock.)

Last Survey, No. 41553 Port of Lon

Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder Brushed "  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 General Observations, Opinion as to Class, &c. Bottom to be caulked  
She is now in an efficient state and eligible to remain as Classed.

Committee's Minute Tuesday March 8<sup>th</sup> 18 81 Senhouse Martin  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.            Survey held at            Date, first Survey            Last Survey            18             
 No. in on the            Master             
 Reg. Book.            Net            Built at            When built            Year.            Month.             
 Tonnage { Gross            By whom built            Owners             
 Under Dk.            Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock             
 (State Name of Dock.)  
 Last Survey, No.            Port of            Classed             
 Present Condition of the  
 Decks            Treenails             
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on             
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18             
 Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

LON666-0216