

(40178)

# Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_ (Received at London Office, 4. 3. 81)

No. in Reg. Book. Survey held at London Date, first Survey \_\_\_\_\_ and Last Survey March 1<sup>st</sup> 1881.

298 on the Machinery of the S. S. "Perim" (Number of Visits 1)

Tonnage, Gross <u>1329</u>	Built at <u>Glasgow</u>	When built <u>1877</u>
Ditto, Net <u>1016</u>	Owners <u>R. W. Causens &amp; Co.</u>	Port belonging to <u>London</u>
Diameter of Cylinder <u>31" x 54"</u>	Engines made by <u>Son. &amp; Glas. Co.</u>	When made <u>1877</u>
Length of Stroke <u>33"</u>	Boilers made by <u>Ditto</u>	When made <u>1877</u>
Pressure of Steam <u>65 lbs.</u>	If Surveyed Afloat or in Dry Dock <u>Pontoon</u>	Classed <u>100 A1</u>
Registered Horse Power <u>150</u>		

Last Survey No. \_\_\_\_\_ Port Lloyds M.C. 5. 77.

## Particulars of Repairs and Examination For Annual Survey

Vessel placed on Pontoon, sea connections examined and found to be in good condition. Propeller and its connections found in good condition. Sail shaft down  $\frac{3}{16}$  in Stern Bush.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed


Entry or Registering Fee ... £ : :  
Survey Fee ... £ — : — : received by me, }  
Certificate (if required) ... £ : : 188 }  
(Travelling Expenses, if any, £ )

Committee's Minute

Assigned

Friday, March, 18th. 1881.

Geo. E. Merriamson  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation

LON665-0264



Submitted that this vessel is  
eligible to remain as classed

M<sub>4</sub> 3.81



© 2021

Lloyd's Register  
Foundation