

ANNUAL SURVEYS.

40,184

No. Survey held at London Date, first Survey (Received at London Office, Feb 16 3 81)
 No. in on the "S. Loik" Master H. Brown Last Survey 28 Feb 1881
 Reg. Book. 32 Net 896 Built at Sunderland When built 1874
 Tonnage Gross 939 Under Dk. By whom built Owners J. Allantson
 Port belonging to London Destined Voyage Imbituba
 If Surveyed Afloat or in Dry Dock Senekilu dry dock
(State Name of Dock.)

Last Survey, No. 38534 Port of London
 Present Condition of the Decks Good Treenails Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places Not seen
 Plank sheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Not seen Copper or Y.M. When put on 1879
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Metal patched on piece of false keel new. Topsides recaulked. She is now in good condition and in my opinion may continue as Classed

Committee's Minute Friday, March, 18th. 1881. Will. B. Davy
 Character assigned Cou 7A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at London Date, first Survey 3rd Mar Last Survey 9th Mar 1881
 No. in on the B^a "Luventa" Master F. Lilluel
 Reg. Book. 590 Net 152 Built at Jersey When built 1855 9
 Tonnage Gross 152 Under Dk. 145 By whom built Deslandes Owners J. Drummond
 Port belonging to London Destined Voyage Berbice
 If Surveyed Afloat or in Dry Dock Gun dock ways & afloat
(State Name of Dock.)

Last Survey, No. 38699 Port of London
 Present Condition of the Decks Good Treenails Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Plank sheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Not seen Copper or Y.M. When put on 1876
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations; Opinion as to Class, &c.

Tested caulking of bottom and found it good new main trussel keel. She appears in good condition and in my opinion may continue as Classed

Committee's Minute Friday, March, 18th. 1881. Will. B. Davy
 Character assigned Cou 7A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

