

# ANNUAL SURVEYS.

40256

(Received at London Office, Tuesday March 29th)

81.

No. \_\_\_\_\_ Survey held at London Date, first Survey March 7 Last Survey March 11 1881  
 No. in on the \_\_\_\_\_ Master W Macey  
 Reg. Book. \_\_\_\_\_  
296 Tonnage 1204 Built at Newcastle When built 1878-8  
 By whom built Schlesinger Owners Angier Bros  
 Port belonging to London Destined Voyage Cardiff  
 If Surveyed Afloat or in Dry Dock Green by SR  
 Last Survey, No. 44705 Port of London Classed 100A. 8-75

Present Condition of the Decks <u>gd</u>	Treenails <u>Paints</u> <u>gd</u>	
Waterways _____	Breasthooks and Stenson _____	Windlass and Capstan <u>gd</u>
Comings _____	Transoms, Pointers, and Crutches _____	Pumps _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Boats _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Masts, Yards, &c. _____
Planksheers _____	Keelsons _____	Condition, how ascertained <u>from SR</u>
Sheerstrakes _____	Clamps and Shelves _____	Sails _____
Topsides _____	Ceiling _____	Anchors, No. of <u>3 Bro. 11 &amp; 12 1/2</u>
Wales _____	Rudder _____	Cables <u>Part on SR</u> <u>gd</u>
Plank (Bottom) and Counter _____	Copper or Y.M. <u>bottom</u> When put on <u>new</u>	Hawsers and Warps _____
Engine Room Skylights <u>gd</u>	Caulking of Bottom, Deck, & Waterways <u>gd</u>	Standing and Running Rigging _____
Coal Bunker, Openings, Lids, &c. <u>gd</u>	Scuppers <u>gd</u>	Cargo and Main Hatchways <u>gd</u>
Hatches _____		

General Observations, Opinion as to Class, &c. Bottom &c coated  
*She is now in an efficient state and eligible to remain as before*

Committee's Minute Friday, April 8th 1881 Senhouse Martiniddle  
 Character assigned 100A TBW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stenson \_\_\_\_\_  
 Windlass and Capstan \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Pumps \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Boats \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Masts, Yards, &c. \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Condition, how ascertained \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Sails \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Anchors, No. of \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Cables \_\_\_\_\_  
 Hawsers and Warps \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_  
 Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

