

ANNUAL SURVEYS.

No. 45297 Survey held at London Date, first Survey April 4th Last Survey April 6th 1881
 No. in on the PS Baron Asy Master J. Verhulst
 Reg. Book 104 Tonnage { Net 573 Built at Newcastle When built 1875 Year. 5 Month. 5
 Gross 961 By whom built Mitchell Owners Antwerp Ship Co
 Under Dk. 747 Port belonging to Antwerp Destined Voyage Antwerp
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock (State Name of Dock.)

Last Survey, No. 48618 Port of London Classed 100 A. 12 80
58 New 1177
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. At present owing to being on the ground the bottom
rotted & the fore end of Wood Bitts had repaired.
She is now in an efficient state and
eligible to remain as classed.
Damage see 220

Committee's Minute Tuesday, April, 19th 1881 Senhouse Martindale
 Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 5/- Paid 19/4/81

No. 45297 Survey held at London Date, first Survey April 4th Last Survey April 6th 1881
 No. in on the PS Baron Asy Master J. Verhulst
 Reg. Book 104 Tonnage { Net 573 Built at Newcastle When built 1875 Year. 5 Month. 5
 Gross 961 By whom built Mitchell Owners Antwerp Ship Co
 Under Dk. 747 Port belonging to Antwerp Destined Voyage Antwerp
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock (State Name of Dock.)
 Last Survey, No. 48618 Port of London Classed 100 A. 12 80
58 New 1177
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. At present owing to being on the ground the bottom
rotted & the fore end of Wood Bitts had repaired.
She is now in an efficient state and
eligible to remain as classed.
Damage see 220
 Committee's Minute Tuesday, April, 19th 1881 Senhouse Martindale
 Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 5/- Paid 19/4/81

