

ANNUAL SURVEYS.

(Received at London Office, 21. 4. 81)

No. 745 Survey held at London Date, first Survey 31 March Last Survey 1 April 18 81
 No. in on the Sw Walter Raleigh Master Purves
 Reg. Book. 745 Net 1492 Built at Glasgow When built 1876 2
 Tonnage Gross 1579 Under Dk. 1283 By whom built Humphreys Owners Rose & Co
 Port belonging to Aberdeen Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Canal dry dock (State Name of Dock.)

Last Survey, No. 46614 Port of Iron Classed 100 A1 5.80
 S.P.N. 1.80
 Present Condition of the
 Decks Good Points Good
 Waterways de Breasthooks and Stenson de
 Comings de Transoms, Pointers, and Crutches de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de
 Planksheers de Keelsons de
 Sheerstrakes de Clamps and Shelves de
 Topsides de Ceiling de
 Wales de Rudder de
 Plank (Bottom) and Counter de Copper or Y.M. - When put on -
 Caulking of Bottom, Deck, & Waterways de
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers de Cargo and Main Hatchways de Hatches de
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated. This vessel appears eligible to remain as classed.

Committee's Minute Friday, April, 22nd 18 81. Thos. Congdon
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 196 Survey held at London Date, first Survey 9 April Last Survey 16 April 18 81
 No. in on the Sh. Douglas Master J. Wilson
 Reg. Book. 196 Net 1428 Built at Lpool When built 1869 1
 Tonnage Gross 1494 Under Dk. 1263 By whom built Poyden Owners S. H. Gars & P. Hamilton
 Port belonging to Lpool Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Replar dry dock (State Name of Dock.)

Last Survey, No. 46591 Port of Iron Classed 8 A1 3.80
 S.P.N. 2.77.
 Present Condition of the
 Decks Good Points Good
 Waterways de Breasthooks and Stenson de
 Comings de Transoms, Pointers, and Crutches de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de
 Planksheers de Keelsons de
 Sheerstrakes de Clamps and Shelves de
 Topsides de Ceiling de
 Wales de Rudder de
 Plank (Bottom) and Counter de Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways de
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers de Cargo and Main Hatchways de Hatches de
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated. This vessel appears eligible to remain as classed. The Ceiling Hatches upon the floors and ships require repairing or renewal, which is to be done at Cardiff. It is intended on the ship's return to submit her for S.P.N. 3.

Committee's Minute Friday, April, 22nd 18 81. Thos. Congdon
 Character assigned 8 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Mr. Walter Raleigh

The Douglas



© 2021

Lloyd's Register
Foundation