

# ANNUAL SURVEYS.

40326

(Received at London Office, (Paid 12/11/81.)

No. \_\_\_\_\_ Survey held at London Date, first Survey 31<sup>st</sup> March Last Survey 23<sup>rd</sup> April 1881

No. in on the Iron S. "Prince Oscar" Master C. Brooks.

Reg. Book. 643 Net 1292 Built at West Hartlepool When built 1864 Year. 10 Month. 10

Tonnage { Gross 1292 By whom built Pile Owners S. R. Graves.  
Under Dk. 1201

Port belonging to Liverpool. Destined Voyage Mauritius.

If Surveyed Afloat or in Dry Dock In Regent Dry Dock.  
(State Name of Dock.)

Last Survey, No. 26159 Port of Iron Classed S.S. Lon. No 3-78 Years assigned. 3.80 Character in Register Book. \*A.1

Present Condition of the Decks <u>good</u>	Treenails <u>rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>D<sup>o</sup></u>	Breasthooks and Stemson <u>D<sup>o</sup></u>	Pumps <u>D<sup>o</sup></u>
Comings <u>D<sup>o</sup></u>	Transoms, <del>Pointers</del> , and Crutches <u>D<sup>o</sup></u>	Boats <u>D<sup>o</sup></u>
Upper Deck Beams & Fastenings <u>D<sup>o</sup></u>	Timbers of the Frames at the Openings <u>D<sup>o</sup></u>	Masts, Yards, &c. <u>D<sup>o</sup></u>
Lower Deck Beams & Fastenings <u>D<sup>o</sup></u>	<del>Ditto</del> ditto at other places <u>D<sup>o</sup></u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>D<sup>o</sup></u>	Keelsons <u>D<sup>o</sup></u>	Sails <u>good</u>
Sheerstrakes <u>D<sup>o</sup></u>	<del>Clamps and Shelves</del>	Anchors, No. of <u>3 B. 1 P. 2 R.</u>
Topsides <u>D<sup>o</sup></u>	Ceiling <u>D<sup>o</sup></u>	Cables <u>complete</u>
Wales <u>D<sup>o</sup></u>	Rudder <u>D<sup>o</sup></u>	Hawsers and Warps <u>sufficient</u>
Plating (Bottom) and Counter <u>D<sup>o</sup></u>	<del>Copper or Y.M.</del> When put on _____	Standing and Running Rigging <u>good.</u>
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways <u>good</u>	
Coal Bunkers, Openings, Lids, &c. _____	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
		Hatches <u>good.</u>

(If a Steam Ship, state if a Report is also sent on the Machinery \_\_\_\_\_)

General Observations, Opinion as to Class, &c. The equipment regulated by tonnage (see equipment supplied as stated below).

The bottom has been examined, cleaned and coated. The rudder pintles rebushed.

One lower anchor and 75 fathoms of chain cable were missing and the following have recently been supplied in their place viz: 1 lower anchor weight ex stock 32-7-7 - proof strain 30-7-1-0. A. S. Jack Superint<sup>nt</sup> - Chester 1<sup>st</sup> April 1881. and 75 fathoms of 1<sup>3</sup>/<sub>16</sub> chain cable - tensile strain 59<sup>1</sup>/<sub>2</sub> tons. breaking strain 82<sup>3</sup>/<sub>4</sub> tons. A. S. Jack Superint<sup>nt</sup> - Chester 22<sup>nd</sup> Nov<sup>r</sup> 1880.

This vessel appears to be eligible to remain as classed.

Committee's Minute Friday, April 20th 1881. J. H. Truscott.

Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_

No. in on the \_\_\_\_\_ Master \_\_\_\_\_

Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_

Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Under Dk. \_\_\_\_\_

Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_

If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____
		Hatches _____

(If a Steam Ship, state if a Report is also sent on the Machinery \_\_\_\_\_)

General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid \_\_\_\_\_ 18 \_\_\_\_\_

Form No. 5 for Annual Survey, when there are no repairs. 4000-6/12/80. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

