

REPORT of SURVEY for REPAIRS, &c.

40335

No. 1546 in Survey held at London Date, first Survey 6 April Last Survey 13 April 1881
 Reg. Book. 1546 on the S.S. Cymbeline Master Coysh
 TONNAGE under Tonnage Deck 1170 Built at Stockton When built 1879
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop Owners Deasman & Port belonging to Hull
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck Residence
 Ditto of Forecastle By whom built Richardson Destined Voyage Odessa
 Gross Tonnage 21259 Surveyed Afloat or in Dry Dock Millwall dock
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 899
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 46974 Port Iron Classed 100 A1.
 REPAIRS, OR EXAMINATION AS PER RULE 6.80

Alterations:— The Comings of the fore Hatchway increased in depth to 3 feet from the iron deck. And the Comings of the after Hatchway increased in depth to 3 feet above the wood deck here, and extended off two beam spaces, but the beams remain intact. The after part of the Hatchway plated over on the top for the two beam spaces referred to. The web plates or shifting beams also increased in depth. ^{in Hatchways} 2. plating used in the alterations.

The Hatchways have been altered to act as feeders for grain cargoes.

Present Condition of the	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Decks	do	Breasthooks and Stemson	do	do	Pumps	do
Waterways	do	Transoms, Pointers, and Crutches	do	do	Boats	four
Comings	do	Timbers of the Frame at the openings	do	do	Masts, Yards, &c.	do
Upper Deck Beams & Fastenings	do	Ditto Ditto at other places	do	do	Condition, how ascertained	from deck
Lower Deck Beams & Fastenings	do	Keelsons	do	do	Sails	well found
Planksheers	do	Clamps and Shelves	do	do	Anchors	No. of 20. 1 S & Kedges
Sheerstrakes	do	Ceiling	do	do	Cables	complete
Topsides	do	Rudder	do	do	Hawsers and Warps	sufficient
Wales	do	Copper (or Y.M.)	When put on	do	Standing & Running Rigging	good
Plank (Bottom) and Counter	do	Caulking of	do	do	Cargo and Main Hatchways	do
Engine Room Skylights	do	Bottom, Deck, & Waterways	do	do	Hatches	do
Coal Bunker, Openings, Lids, &c.	do	Scuppers	do	do		

This vessel appears in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £ : : : received by me, }
 2/5/81 Special ... £ 2 : 2 : 5 May 1881 }
 Certificate (if required) } £ : 5 :
 to be sent as per margin... }
 (Travelling Expenses, if any, £)

Committee's Minute Tuesday, May 3rd 1881.
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping. J. H. Bondson
 © 2021 Lloyd's Register Foundation
 LON665-0461

If a Surveyor is not present, state in the Report is also sent on the Machinery

(Insert Character precisely as in Register Book.)

Cymbeline



© 2021

Lloyd's Register
Foundation

BELOW OF SUBAER FOR