

40422  
Report of Survey for Repairs of Engines and Boilers.

To. \_\_\_\_\_ (Received at London Office, 21. 5. 81.)  
No. in Survey held at London Date, first Survey and Last Survey May 11 1881.  
No. in Reg. Book. 548 on the Machinery of the S.S. "Dunrobin Castle" (Number of Visits 1)  
Age, Gross 2811 Built at Glasgow When built 1875  
Ditto, Net 1784 Owners D. Currie & Co. Port belonging to London.  
Diameter of Cylinder 47" + 75" Engines made by R. Napier & Sons When made 1875  
Length of Stroke 48" Boilers made by Ditto When made 1875  
Pressure of Steam 60 lbs. If Surveyed Afloat or in Dry Dock (State name of Dock.)  
Registered Horse Power 300. Classed 100A1  
Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Particulars of Repairs and Examination For Annual Survey  
(State cause of Repairs.)

Vessel placed in dry dock sea connections examined and found to be in good condition. Propeller and its connections in good condition. Tail shaft found to be a good working fit in Stern Bush.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears to be eligible to remain as classed

Entry or Registering Fee... £ : :  
(per Section 27.)  
Survey Fee (per Section 28) ... £ : : received by me, }  
Certificate (if required) ... £ : : 188 }  
to be sent as per margin.  
Travelling Expenses, if any, £ \_\_\_\_\_

Committee's Minute \_\_\_\_\_ Tues'day, May 21st 1881.  
Assigned \_\_\_\_\_

Geo. F. Morrison  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.  
Lloyd's Register Foundation

Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be filled in by the Surveyor.

(Insert Character precisely as in the Register Book.)

LON 665-5571



It is submitted that this  
vessel is eligible to  
be named or classed

M  
20/5/81



© 2021

Lloyd's Register  
Foundation