

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 26. 5. 81)

No. in Survey held at London Date, first Survey _____ Last Survey May 15 1881
 Reg. Book. 318 on the S Thyatira (Composite) Master C Lawrence
 TONNAGE under Tonnage Deck 855 Built at Aberdeen When built 1867
 Ditto of Spar Deck, or Awning Deck _____ Owners G Thompson & Co Port belonging to Aberdeen
 Ditto of Poop _____
 Ditto of Raised Qr. Dk. _____
 Ditto of Houses on Deck _____
 Ditto of Forecastle _____
 Gross Tonnage 962 Residence _____
 Crew Space, as per Rule _____ By whom built Flood Destined Voyage Australia
 Register Tonnage, out on Beam 962 If Surveyed Afloat or in Dry Dock _____
 Engine Room _____ (State Name of Dock) _____
 Reg. Tons as St mer, out on Bm. _____

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. _____ Character in Register Book. _____
 Last Survey, No. 40289 Port de Lou Classed 17A1-588
 REPAIRS, OR EXAMINATION AS PER RULE _____ SS Lon 77 5.81
 Cause of Repairs to be clearly stated. HT Lon 77.

The owners solicits an improved class under amended Table I for composite ships.

Having examined her I found her in excellent condition and according to the 1st entry her materials are of the highest class. The stempost, stem, deadwood, & the outside planking above the depth of hold is of East India Teak, including the Wales, Blackstrakes, Ipsides, Sheerstrakes, Planksheers and Waterways of East India Teak.

Present Condition of the		Treenails	Bolts		Windlass and Capstan
Decks	Good			Good	Good
Waterways	"	Breasthooks and Stenson		"	Pumps
Comings	"	Transoms, Pointers, and Crutches		"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained
Planksheers	"	Keelsons		"	Sails
Sheerstrakes	"	Clamps and Shelves		"	Anchors No. of 3 Bns. St & Redgs
Topsides	"	Ceiling		"	Cables Part on St
Wales	"	Rudder		"	Hawsers and Warps
Plank (Bottom) and Counter	"	Copper (or Iron) Metal When put on	None	"	Standing & Running Rigging
Engine Room Skylights	"	Caulking of		"	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways		"	Hatches
Scuppers	Good			"	

General Observations, Opinion as to Class, &c. She is in an efficient state and respectfully recommends her to the Committee's favourable consideration to be classed as follows viz-

- under amended Table I - 16 lbs East India Teak
2 do yellow Metal Bolts
1 do Roof
19A1

The Amount of Entry Fee ... £ : : received by me, _____
 Special ... £ : : _____
 Certificate (if required) to be sent as per margin... £ : : _____
 (Travelling Expenses, if any, £ _____)
 Committee's Minute _____
 Character assigned _____

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Friday, May, 27th 1881.

Raised to 19A1



