

Damage Repairs
REPORT of SURVEY for REPAIRS, &c.

407456

(Received at London Office, 25/5/81)

No. 261 on the SS Agnes Date, first Survey May 18 Last Survey May 21st 1881
 No. in Survey held at Gravesend Reg. Book. 1287 Master Holbeck
 TONNAGE under Tonnage Deck 1287 Built at W Hartlepool When built 1877 MONTH 9
 Ditto of Spar Deck, or Afters Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1608 Owners R Irvine & Co Port belonging to W Hartlepool
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as S^rmer, cut on Bm. 1042 Residence
 By whom built Irvine Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Gravesend Afloat & Laden
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Years assigned. 100 A. 2. 81 Character in Register Book.

Last Survey, No. 28071 Port Iron

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

*At present owing to damage
 Repairs Upper part of Top Gallant Forecastle
 Starboardside 2 doubling plates put over 2 broken
 plates and well rivetted making them stronger than
 the original one length of stringer angle iron & one length
 of angle iron to secure the Wood Top Gallant Rail,
 2 lengths of Bone Rail Eng Deck
 Top Gallant Forecastle Deck caulked*

Present Condition of the	Where seen	Good	Treenails	Carrots where seen	Good	Windlass and Capstan	Good
Decks			Breasthooks and Stemson			Pumps	"
Waterways		"	Transoms, Pointers, and Crutches			Boats	"
Comings		"	Timbers of the Frame at the openings			Masts, Yards, &c.	"
Upper Deck Beams & Fastenings		"	Ditto Ditto at other places			Condition, how ascertained	From SH
Lower Deck Beams & Fastenings		"	Keelsons			Sails	Good
Planksheers		"	Clamps and Shelves			Anchors No. of 3 No. 10 & 1 No. 8	
Sheerstrakes		"	Ceiling			Cables Part on SH	Good
Topsides		"	Rudder		When put on	Hawsers and Warps	"
Wales		"	Copper (or Y.M.)			Standing & Running Rigging	"
Plank (Bottom) and Counter		"	Caulking of Bottom, Deck, & Waterways		Good	Cargo and Main Hatchways	Good
Engine Room Skylights	Good		Coal Bunker, Openings, Lids, &c.	Good		Hatches	"
Scuppers	Good		General Observations, Opinion as to Class, &c.				

*She is now in a efficient-state
 and eligible to remain as classed.*

Damage Fee £ 2 2 0

The Amount of Entry Fee ... £ 4 : 4 : 4 received by me, JH
 Special ... £ 1 : 1 : 1 same 1881
 Certificate (if required) to be sent as per margin... } £ : 5 :

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £ 1-18-6)
 2 rems
 Committee's Minute

Tuesday, May, 31st 1881.

Character assigned

100 A



© 2021
 Lloyd's Register
 Foundation

JH

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.