

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey May 23^d Last Survey June 2^d 18 81
 No. in on the SS Palmyra Master Alexander Munro
 Reg. Book. 61 Net 707 Built at Newcastle When built 1866 Year. 1 Month.
 Tonnage Gross 960 Under Dk. 822 By whom built Palmer Owners Sen Stan Ship Co.
 Port belonging to London Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock
 (State Name of Dock.)

Last Survey, No. 26153 Port of Dron Classed 90A-3.80.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Breasthooks and Stemson
 Comings Raised 3/4 in grain barges. Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Vales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained From St
 Sails Good
 Anchors, No. of 4 Birs St & 1 Bids
 Cables Part on deck Good
 Hawesers and Warps
 Standing and Running Rigging
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 General Observations, Opinion as to Class, &c. During to damage. Renewed one butt strap and several rivets in the bottom. Cement renewed where broken.
Damage to 2-2-1
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, June, 16th 1881. Senhouse Martindale
 Character assigned 90A TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
B.S.O. subject to Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 in on the Master
 Book. Year. Month.
 Tonnage { Net Built at When built
 Gross By whom built Owners
 Under Dk.
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Vales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawesers and Warps
 Standing and Running Rigging
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18