

# Report of Survey for Repairs of Engines and Boilers.

with 40565-Lon

No. 304 (Received at London Office, 28/11/81)

No. in Reg. Book. Penarth Survey held at Penarth Date, first Survey Nov 14 Last Survey Nov 18 1881

153 on the Machinery of the Iron S.S. "Viceroy" (Number of Visits Two)

Tonnage, Gross 2463 Built at London When built 1871

Ditto, Net 1864 Owners R. & H. Green Port belonging to London

Diameter of Cylinder 38" x 66" Engines made by Ravenhill Hodgson & Co. When made 1871

Length of Stroke 39" Boilers made by Do Do When made 1871

Pressure of Steam 60 lbs If Surveyed Afloat or in Dry Dock Penarth Dock (State name of Dock.)

Registered Horse Power 240 Years assigned. 100A.1 Character in Register Book. 2.81

Last Survey No. 130 Port B.M.L. 180

## Particulars of Repairs and Examination

(State cause of Repairs.)

Main boiler safety-valves tested under steam and found to blow satisfactorily at 58 lbs. pressure and 60 lbs. per sq. in.

## General Observations, Opinion, and Recommendation:—

This Vessel's Machinery is now in good and efficient condition as far as seen and entitles her in my opinion to remain as classed.

Entry or Registering Fee... £ : :  
(per Section 27.)

Survey Fee (per Section 28) ... £ 1 : 1 : received by me, 26/11 1881


Certificate (if required) ... £ : :  
to be sent as per margin.

(Travelling Expenses, if any, £ 5/-)

Committee's Minute Friday, December. 2nd. 1881.

Assigned

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation

LON666-0164



Viceroy



© 2021

Lloyd's Register  
Foundation