

SS No. 2. 40568
PORT of SURVEY for REPAIRS, &c.

(Received at London Office, Friday, October, 28th, 1881)

held at

London

Date, first Survey

Sept 7th

Last Survey

Oct 27th

1881

432 on the

SS Glenatney

Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck

2065

Ditto of Spar Deck, or Awning Deck

Built at

Glasgow

When built

1873

Ditto of Poop

Owners

M Gregor & Co

Port belonging to

Glasgow

Ditto of Houses on Deck

Residence

Ditto of Forecastle

Gross Tonnage

2143

Crew Space, as per Rule

By whom built

Sen & Glas & Co

Destined Voyage

Singapore & Shanghai

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

1400

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Greens St & afloat

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Classed

100A 12. 80.

SS Sen M 178

Last Survey, No.

28758

Port

Iron

REPAIRS, OR EXAMINATION AS PER RULE

Special Survey No. 2.

Cause of Repairs to be clearly stated.

at the present time placed in the Dry Dock the timbers and bolting equal to 3 shakes taken up on both sides examined and found good, and the cement adhering firmly to the Iron and thickened where required. Bottom & coated

The chain cables ranged on the Quay at the Bows and examined. The floor bottom and Cement examined under boilers and stoke hole foot plates and the Cement repaired where necessary.

The Windlass and purchase all of Iron.

Present Condition of the		Treenails	Rivets		Windlass and Capstan	
Decks	Good			Good		Good
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	Examined
Planksheers	"	Keelsons		"	Sails	Good
Sheerstrakes	"	Clamps and Shelves		"	Anchors No. of & Pres St & Pedes	
Topsides	"	Ceiling		"	Cables	Good
Wales	"	Rudder		"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or P.M.) Coated When put on	Good	"	Standing & Running Rigging	"
Engine Room Skylights	Good	Caulking of		"	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good	"	Hatches	"
Scuppers	Good			"		

General Observations, Opinion as to Class, &c.

She is now in an efficient state and eligible to remain as classed and to be marked SS Sen No 2-1881 in the Register Book

Senhouse Martindale

J. W. Miles

The Amount of Entry Fee ... £ 4 : 4 : 0 received by me, A.B.

11/12/81 Special ... £ 4 : 4 : 0 7/12/1881

Certificate (if required)

to be sent as per margin... £ 5 : 0 : 0

(Travelling Expenses, if any, £)

Committee's Minute

Friday, December, 2nd, 1881.

Character assigned

100A 1

Lloyd's Reg 11. 81

S. S. No 2-81

Subject to DTB

ROBT. EDWD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.



© 2021

Lloyd's Register Foundation

LON 666-0172