

(40657)

29. 6. 81

No. in  
Reg. Book.

Tonnage, Gross 3705  
Ditto, Net 2381  
Diameter of Cylinder 51" x 88"  
Length of Stroke 57"  
Pressure of Steam 75 lbs.  
Registered Horse Power 500

Owners D. Currie & Co.

*(State cause of Repairs.)*

Vessel placed in dry dock, sea connections examined and found to be in good condition. Propeller and its connections sound. Tail shaft found to be a good fit in stern bush.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed

Entry or Registering Fee... <i>(per Section 27.)</i>	... £	:	:	
Survey Fee <i>(per Section 28)</i> ...	... £	—	—	received by me,
Certificate (if required) <i>to be sent as per margin.</i>	... £	:	:	188
<i>(Travelling Expenses, if any, £.....)</i>				

*Geo. E. Merriam.*  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

*Committee's Minute* *Friday, July, 29th 1881.*

*Assigned*

# LR

Lloyd's Register  
Foundation

LON 666 - 0328

(State if Report is also sent on the Hull of the Ship .....)

Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

*(Insert Character precisely as in the Register Book.)*



It is submitted that this  
vessel is eligible to  
remain as classed

Mr 28/4/81



© 2021

Lloyd's Register  
Foundation