

ANNUAL SURVEYS.

40683

No. 65 Survey held at London Date, first Survey 2 August Last Survey 4 August 1881
 on the "S. Jaranalli" Master Hird
 Reg. Book. 65 Net 1188 Built at P. Glasgow When built 1877
 Tonnage Gross 1199 Under Dk. 1042 By whom built Duncan Owners Neslie
 Port belonging to Glasgow Destined Voyage 6 days
 If Surveyed Afloat or in Dry Dock Regent dry dock (State Name of Dock.)

Last Survey, No. 27542 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treenails Good Breasthooks and Stemson Good
 Waterways do Transoms, Pointers, and Crutches do Windlass and Capstan Good
 Comings do Timbers of the Frame at the Openings do Pumps two
 Upper Deck Beams & Fastenings do Ditto ditto at other places do Boats six
 Lower Deck Beams & Fastenings do Keelsons do Masts, Yards, &c. do
 Planksheers do Clamps and Shelves do Condition, how ascertained from deck
 Sheerstrakes do Ceiling do Sails well found
 Topsides do Rudder do Anchors, No. of 50 lbs. 15 Hedges
 Wales do Copper or Y.M. When put on Cables complete
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways do Hawseers and Warps sufficient
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Standing and Running Riggings good
 (If a Steam Ship, state if a Report is also sent on the Machinery) Scuppers do Cargo and Main Hatchways do Hatches do
 General Observations, Opinion as to Class, &c.


Bottom recoated. This vessel appears eligible to remain as classed.
Surveyed with ballast all over the hold.
It is intended to submit the vessel for S.S. W. on her return.

Committee's Minute Tuesday, August, 11th 1881. W. B. Douglass
 Character assigned A.B. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 on the Master
 Reg. Book. Net Built at When built
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails Breasthooks and Stemson
 Waterways Transoms, Pointers, and Crutches Windlass and Capstan
 Comings Timbers of the Frame at the Openings Pumps
 Upper Deck Beams & Fastenings Ditto ditto at other places Boats
 Lower Deck Beams & Fastenings Keelsons Masts, Yards, &c.
 Planksheers Clamps and Shelves Condition, how ascertained
 Sheerstrakes Ceiling Sails
 Topsides Rudder Anchors, No. of
 Wales Copper or Y.M. When put on Cables
 Plank (Bottom) and Counter Caulking of Bottom, Deck, & Waterways Hawseers and Warps
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Standing and Running Riggings
 (If a Steam Ship, state if a Report is also sent on the Machinery) Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

LON066-0360

L. R. R.



© 2021

Lloyd's Register
Foundation